



Research-fueled Security Services



\ WHITE PAPER \

Reverse Engineering of DAL-A Certified Avionics: Collins' Pro Line Fusion — AFD-3700

Ruben Santamarta
Security Researcher, IOActive

April 19, 2022

Contents

Notices	3
Introduction.....	4
Research Context.....	4
Pro Line Fusion® and the AFD-3700.....	5
Approach.....	16
Attack Surface	17
Impact and Safety Implications	19
Affected Aircraft	29
Technical Analysis	31
Reverse Engineering Notes.....	31
Attacking a LynxOS-178-based System	33
Security Boundaries	35
AFDR-3700 Boot Sequence	35
AFD-3700 Health Monitor Application: hm_main	37
Vulnerable SNMP Daemon in hm_main	39
Exploitation	44
AFD-3700 Inter-Partition Communication Mechanisms and Network Connectivity	49
network.cfg Analysis.....	52
Following the Packets	58
Finding the Path to snmpd.....	63
WSAStartup.....	64
Create Socket.....	65
Bind Socket	66
Recvfrom	67
Attack Vectors for snmpd	71
1. VM1	71
2. Avionics System LAN: 10.129.25.0 in the ASL.....	72
Attacking AFDR-3700 Drivers	75
PCIE.dldd: RESET_MIB_DATA IOCTL Double Fetch.....	75
MERGE.dldd: Memory Corruption Due to Integer Overflow	77
Conclusions	78
Acknowledgements.....	83

Notices

No Warranties or Representations

The information presented herein is provided “AS IS” and IOActive disclaims all warranties whatsoever, whether express or implied. Further, IOActive does not endorse, guarantee, or approve, and assumes no responsibility for nor makes any representations regarding the content, accuracy, reliability, timeliness, or completeness of the information presented. Users of the information contained herein assume all liability from such use.

Publicly Available Material

All source material referenced in this presentation was obtained from the Internet without restriction on use.

Fair Use

This primary purpose of this presentation is to educate and inform. It may contain copyrighted material, the use of which has not always been specifically authorized by the copyright owner. We are making such material available in our efforts to advance understanding of cyber safety and security. This material is distributed without profit for the purposes of criticism, comment, news reporting, teaching, scholarship, education, and research, and constitutes fair use as provided for in section 107 of the Copyright Act of 1976.

Trademarks

IOActive, the IOActive logo and the hackBOT logo are trademarks and/or registered trademarks of IOActive, Inc. in the United States and other countries. All other trademarks, product names, logos, and brands are the property of their respective owners and are used for identification purposes only.

No Endorsement or Commercial Relationship

The use or mention of a company, product or brand herein does not imply any endorsement by IOActive of that company, product, or brand, nor does it imply any endorsement by such company, product manufacturer, or brand owner of IOActive. Further, the use or mention of a company, product, or brand herein does not imply that any commercial relationship has existed, currently exists, or will exist between IOActive and such company, product manufacturer, or brand owner.

Copyright

Copyright © 2022 IOActive, Inc. All rights reserved. This work is protected by US and international copyright laws. Reproduction, distribution, or transmission of any part of this work in any form or by any means is strictly prohibited without the prior written permission of the publisher.

Abstract

Modern avionic systems are designed according to the Integrated Modular Avionics concept. Under this paradigm, safety-certified avionic applications and non-critical airborne software share the same computing platform but are running at different partitions. In this context the underlying safety-critical certified RTOS provides the logical isolation, which should prevent unintended interactions between software with different criticalities.

This paper provides a comprehensive analysis of the architecture and vulnerabilities found on the Adaptive Flight Display component of the Collins Aerospace's Pro Line Fusion solution. This integrated avionics system, deployed both in military and commercial aircraft, is certified as DO-178B/C Design Assurance Level A.

Introduction

Research Context

A series of precautions must be considered within the context of a vulnerability disclosure that affects the aviation industry, where even a minimal inaccuracy may be used to discredit and invalidate the research as a whole. In IOActive's experience, affected entities in the aviation sector tend to maintain an opaque attitude, compared with other industries. Therefore, the burden of the proof is almost entirely on the researcher's side, which poses a significant challenge in such a complex field.

This specific scenario requires not only a comprehensive description, a plausible explanation, and a complete technical analysis, but also enough evidence to sustain the conclusions of the research. Additionally, it is worth mentioning the inability to physically access neither a fully working aircraft nor a simulator to legally test the attacks in a live environment.

Neither Collins Aerospace nor its customers or partners provided any technical support to IOActive: the research has been performed by following a static black-box¹ approach, solely based on the reverse engineering of the firmware, without having physical access to the hardware.

The main objectives of this research are the following:

- Demonstrate that the target in scope is actually certified for safety-critical operations
- Demonstrate that the target, a safety-critical certified avionics component, can be compromised, either remotely or via inter-partition attacks, during any phase of flight
- Demonstrate the potential safety implications derived from a compromised target

The structure of this paper, as well as its narrative, have been conceived according to these objectives. All content in this paper has been included for a reason, even if it appears obvious

¹ No access to source code, documentation, or resources beyond what it is publicly available.

or redundant. The reader should carefully note all the references that can be found throughout the document, as they point out external sources that can be used to contrast the claims presented herein. Special effort has been put into introducing those concepts for which there are no references available, without covering in detail others for which a large amount of literature is already available, such as IMA².

Disclosure

IOActive and Collins Aerospace have been coordinating the issues herein described since March 2021.

Several pre-publication versions of this paper were shared with Collins Aerospace. In their recent letter dated April 7, 2022 they acknowledge the vulnerabilities (“defects” according to their nomenclature) described in this research and will proceed “to make updates which will address issues you’ve described as part of our next major release with development starting this year. Once changes have been made to the software, verification and certification will be required across multiple configurations and platforms”.

They also asked for deletion of two statements regarding one of the post-exploitation scenarios as well as the list of the impacted aircraft. Additionally, their assessment of the potential safety implications is not aligned with ours, as they state that ‘defects do not adversely impact operational safety’.

IOActive has highlighted these three disputed statements in the paper, to provide the reader a clear view of both Collins Aerospace and IOActive respective positions.

[Disputed statement 1](#)

[Disputed statement 2](#)

[Disputed statement 3](#)

Pro Line Fusion[®] and the AFD-3700

Pro Line Fusion from Collins Aerospace is an integrated avionics suite (see Figure 2).^{3 4} Its architecture is comprised of multiple systems, and it provides safety-critical functionality.

Pro Line Fusion[®]

Unprecedented safety, efficiency and predictability on every mission

Figure 1. Pro Line Fusion Banner - Collins Aerospace Website

² https://en.wikipedia.org/wiki/Integrated_modular_avionics

³ <https://www.collinsaerospace.com/what-we-do/Business-Aviation/Flight-Deck/Pro-Line-Fusion>

⁴ Challenger 604 – Pro Line Fusion Tour <https://www.youtube.com/watch?v=BbV9iqdfVaM>




Figure 2. Pro Line Fusion Avionics Suite - Challenger CL604, Bombardier

In the context of the Pro Line Fusion, the Electronic Flight Instrumentation System (EFIS) implements at least three⁵ model AFD-3700 Display Units (DUs, see Figure 3) that provide display and control capabilities for features such as:

- Synthetic Vision System (SVS)
- Advanced Terrain Functions (ATF)
- Traffic Alert Collision Avoidance System (TCAS)
- Engine Indicating and Crew Alerting System (EICAS)
- Attitude Heading and Reference System (AHRS)
- Flight Management System (FMS)
- Weather Radar System (WXR)
- File Server Application (FSA)
- Flight Display System Application (FDSA)
- Radio Tuning System Application (RTSA)

It is important to clarify that the extent of these aforementioned applications is not limited to the scope of the AFD-3700, but also usually integrate with multiple systems across different

⁵ Two in light helicopters/aircraft.

components in the aircraft. For instance, the EICAS functional application in the AFD-3700 DU may consume data from different sensors and systems.



Figure 3. Display Units (AFD-3700)⁶

At the factory, Collins Aerospace loads the DUs with the runtime system AFDR-3700 (Adaptive Flight Display Runtime), which is certified as DO-178B/C Design Assurance Level (DAL) A⁷. The DAL-A is associated with functions whose anomalous behavior could cause or contribute to a catastrophic failure condition for the aircraft. The AFDR-3700 consists of the real-time operating system (RTOS), drivers, configuration tables, and applications that enable the DU to properly operate as well as to perform field loading operations both via USB and wirelessly through an external data loader, such as the IMS.⁸ Later on, aircraft manufacturers can load the DU with the proper functional applications (EICAS, FMS, etc.) and configuration tables required for their respective aircraft (see Figure 4 and Figure 5).

⁶ https://support.cessna.com/custconf/pageview?as_id=46540

⁷ <https://en.wikipedia.org/wiki/DO-178B>

⁸ <https://www.youtube.com/watch?v=s20Xjq4HnEQ>



Figure 4. AFD-3700 Nameplates




Figure 5. AFD-3700 Components

As depicted in Figure 5. AFD-3700 Components, the AFD-3700 manages the AFD hardware and software resources, and provides common services that let the functional applications run. This essentially means that a compromised AFD-3700 Runtime may directly influence the loaded functional applications.

The files that enabled this research were retrieved from the publicly accessible Rockwell Collins support portal (see Table 1).⁹ This server exposed unauthenticated downloads, including the Black Label (production release) version of the ARINC665-3 Loadable Software Parts of AFDR-3700 intended for distribution to King Air¹⁰ aircraft.

Table 1. Exposed files

File	Description
COL_Application01.001	LynxOS-178 Kernel Downloadable Image (KDI) (AFDR-3700)
COL_Application01.002	Rockwell Collins AFDR-3700 User Filesystem
COL_Application01.luh	A665-3 Load Upload Header
COL_Table01.001	Product version and certification
COL_Table01.002	Product version and certification
COL_Table01.004	VCT for the following functional applications: EICAS-6000, RTSA-6000, and ECDA-6000
COL_Table01.005	VCT for the following functional application: ATF-3500
COL_Table01.003-033	AFD Functional Configuration Tables
COL_Table01.luh	A665-3 Load Upload Header
FILES.lum and LOADS.lum	A665-3 LUM files
COL_Table01.012 (cached)	<p>IOActive found a version of this file (accessible via Google searches) that was different from the file downloaded from the server. The cached version is the SL03.vct file for the FDSA-6500 functional application.</p> <div> <p>https://portal.rockwellcollins.com > COL_Table01.012</p> <p>Virtual Machine Configuration Table // File Name: S3-SL01.VCT</p> <p>...</p> <p>... <VM0> // VCT2177 GroupIds=; // VCT1187 LogicalName=AFDR-3700; // VCT1188 ... <VM1> // VCT2178 GroupIds=; // VCT2147 LogicalName=FDSA-6500; ...</p> </div>

⁹ https://web.archive.org/web/20210119190712/https://portal.rockwellcollins.com/web/support-self-service/kidde-claim/-/document_library/T8Mdh06qCThZ/view/1910640?_com_liferay_document_library_web_portlet_DLPortlet_INSTANCE_T8Mdh06qCThZ_redirect=https%3A%2F%2Fportal.rockwellcollins.com%3A443%2Fweb%2Fsupport-self-service%2Fkidde-claim%3Fp_p_id%3Dcom_liferay_document_library_web_portlet_DLPortlet_INSTANCE_T8Mdh06qCThZ%26p_p_lifecycle%3D0%26p_p_state%3Dnormal%26p_p_mode%3Dview

¹⁰ https://en.wikipedia.org/wiki/Beechcraft_Super_King_Air

File	Description
COL_Table01.003 (cached)	<p>IOActive found a version of this file (accessible via Google searches) that was different from the file downloaded from the server. The cached version is the SL02.vct file for the FSA-6000 functional application.</p> <div> https://portal.rockwellcollins.com > COL_Table01.003 Virtual Machine Configuration Table // File Name: S1-SL02.VCT SysRamMemLim=52428800; // VCT1203 PersStorOnLocalLim=512; // VCT1206 <VM0> <VM1> // VCT53 GroupIds=; // VCT2212 LogicalName=FSA-6000; ... </div>

An initial analysis of the COL_Application01.001 and COL_Application01.002 files revealed an AFDR-3700 version dating back to 2014 with part number 810-0346-001 (see Figure 7), which matches the official part number referenced in official documents from Collins (see Table 1. Exposed files).

Course Syllabus: 523-0821913

COURSE TITLE: Pro Line Fusion King Air
Pilot Training

EQUIPMENT TYPE:

EQUIPMENT	NOMENCLATURE	PART NUMBER
Flight Guidance Computer	FGC-3000	822-1108-147, -131, -132
Flight Guidance Panel	FGP-3000	822-1107-103
Servo	SVO-3000	822-1168-001, -002, -003
VHF Comm Transceiver	VHF-4000	822-1468-110 822-1468-310 (datalink)
Communications Management Unit	CMU-4000	822-1739-003
...		
Software: Adaptive Flight Display Runtime	AFDR-3700	810-0346-001

Figure 6. Pro Line Fusion Course for King Air¹¹

¹¹ <https://portal.rockwellcollins.com/documents/1904088/2147097/SYB5230821913.pdf/ed9d4f14-65f2-764d-78ab-bd8995b30f61>

3E3200	54797065	20414644	522D3337	30302020	20202020	20202020	20202020	20202020	Type AFDR-3700
3E3220	20202020	20202020	20202020	20202020	000A426C	61636B20	4C616265	6C202020	Black Label
3E3240	20202020	20202020	20202020	20202020	20202020	20202020	20202020	20202020	
3E3260	2020000A	454D4F44	20313220	20202020	20202020	20202020	20202020	20202020	EMOD 12
3E3280	20202020	4D465220	30454644	30202020	20202020	000A504E	52203831	302D3033	MFR 0EFD0 PNR 810-03
3E32A0	34362D30	30312020	20202020	20202020	20202020	2020444D	46203230	31342D30	46-001 DMF 2014-0
3E32C0	392D3136	20200D0A	526F636B	77656C6C	20436F6C	6C696E73	2C20496E	632E2043	9-16 Rockwell Collins, Inc. C
3E32E0	65646172	20526170	6964732C	20494120	35323439	38205553	000A4352	432D3332	edar Rapids, IA 52498 US CRC-32
3E3300	20464644	43434537	38000000	00000000	00000000	00000000	00000000	00000000	FFDCCE78
3E3320	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	
3E3340	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	
3E3360	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	
3E3380	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	
3E33A0	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	
3E33C0	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	
3E33E0	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	
3E3400	54797065	20414644	522D3337	30302020	20202020	20202020	20202020	20202020	Type AFDR-3700
3E3420	20202020	20202020	20202020	20202020	000A4641	41205453	4F204331	31336120	FAA TSO C113a
3E3440	20202020	20202020	20202020	20202020	20202020	20202020	20202020	20202020	
3E3460	2020000A	444F2D31	37384220	4C657665	6C20412F	44202020	20202020	20202020	DO-178B Level A/D
3E3480	20202020	4D465220	30454644	30202020	20202020	000A504E	52203831	302D3033	MFR 0EFD0 PNR 810-03
3E34A0	34362D30	30312020	20202020	20202020	20202020	2020444D	46203230	31342D30	46-001 DMF 2014-0
3E34C0	392D3136	20200D0A	526F636B	77656C6C	20436F6C	6C696E73	2C20496E	632E2043	9-16 Rockwell Collins, Inc. C
3E34E0	65646172	20526170	6964732C	20494120	35323439	38205553	000A4352	432D3332	edar Rapids, IA 52498 US CRC-32
3E3500	20363644	38353743	46000000	00000000	00000000	00000000	00000000	00000000	66D857CF

Figure 7. Detail of *nameplate.txt* and *TSO_nameplate.txt* (C113a) Files¹² Found in *Col_application01.002* (AFDR-3700 USRFS)

LynxOS-178¹³ is a POSIX/ARINC-653 conformant real-time operating system (RTOS) that has been granted DO-178B/C DAL-A certification by FAA/EASA regulators for safety-critical applications. The origin of the LynxOS-178 is VMOS, an avionics RTOS developed by Rockwell Collins.

The following statement¹⁴ is publicly available on the Lynx (manufacturer of LynxOS, which at the time was named LynxWorks) website, showing that LynxOS-178 is used in several other components besides the AFD runtime:

Earlier this year, LynxWorks received Advisory Circular AC 20-148 approval from the FAA for reusable software components (RSC) authorized for the LynxOS-178 operating system used in the Rockwell Collins Adaptive Flight Display Runtime, Common Computing Module Runtime, Data Concentration Module Runtime and Synthetic Vision Module Runtime for Pro Line Fusion.

Figure 8. LynxOS-178 Running in Additional Components

Table 2 provides the complete list of the archives that were extracted from the 'Col_Application.002' file system.

Table 2. Rockwell Collins USRFS files

¹²

[https://rgl.faa.gov/Regulatory_and_Guidance_Library/rgTSO.nsf/0/dd968e96d184041e862579f10070b452/\\$FILE/TSO-113a.pdf](https://rgl.faa.gov/Regulatory_and_Guidance_Library/rgTSO.nsf/0/dd968e96d184041e862579f10070b452/$FILE/TSO-113a.pdf)

¹³ <https://www.lynx.com/products/lynxos-178-do-178c-certified-posix-rtos>

¹⁴ <https://www.lynx.com/press-releases/lynxos-178-rtos-deployed-by-rockwell-collins-in-pro-line-fusion-series-of-flight-deck-systems>

File	Type	Description
SL01.vct	LynxOS-178 virtual machine (VM) configuration table	VCT for Simple Display Application (SDA)
SL03.vct	LynxOS-178 VM configuration table	VCT for the following functional applications: EICAS-6000, RTSA-6000, and ECDA-6000
SL04.vct	LynxOS-178 VM configuration table	VCT for the following functional application: ATF-3500
nameplate.txt	Text file	Product and certification information
tso_nameplate.txt	Text file	Product and certification information
pcieinfo_default.info	LynxOS-178 driver info file	Default info file for PCIE driver
pcieinfo_policing_on_100MbsFull.info	LynxOS-178 driver info file	Unused info file for PCIE driver
pcieinfo_policing_on_autoneg.info	LynxOS-178 driver info file	Unused info file for PCIE driver
afdx_asl_info_0	LynxOS-178 driver info file	Default info file for AFDX driver
afdx_asl_info_default_0	LynxOS-178 driver info file	Default info file for AFDX driver
network.cfg	Proprietary Collins Aerospace file	Network (Avionics System LAN) Configuration file for AFDX and PCIE drivers
norflash.info	LynxOS-178 driver info file	Default info file for NORFLASH driver
iod.info	LynxOS-178 driver info file	Default info file for IOD driver
touch.info	LynxOS-178 driver info file	Default info file for TOUCH driver
rs422.info	LynxOS-178 driver info file	Default info file for RS422 driver
apm_info.info	LynxOS-178 driver info file	Default info file for APM driver
rtc.info	LynxOS-178 driver info file	Default info file for RTC driver
fat32fs.info	LynxOS-178 driver info file	Default info file for FAT32FS driver
usb_20rs.info	LynxOS-178 driver info file	Default info file for USB_20RS driver

File	Type	Description
ge4A.info	LynxOS-178 driver info file	Default info file for GE4 driver
ge4B.info	LynxOS-178 driver info file	Unused info file for GE4 driver
gecko.info	LynxOS-178 driver info file	Default info file for GECKO driver
merge.info	LynxOS-178 driver info file	Default info file for MERGE driver
ati_info_0	LynxOS-178 driver info file	Default info file for ATI_DRVR driver
pdkminfo_afd3700.info	LynxOS-178 driver info file	Default info file for PDKM driver
vm0.pct	Proprietary Collins Aerospace file	VM0 process configuration table
nand_system.info	LynxOS-178 driver info file	Default info file for NAND_FS_DRVR driver
ONFI_nand_bank{0-7}.info	LynxOS-178 driver info file	Info files related to NAND_FS_DRVR
drmlite_c1.info	LynxOS-178 driver info file	Info file related to DRMLITE driver
drmlite_c4.info	LynxOS-178 driver info file	Info file related to DRMLITE driver
drmlite_nodeferred.info	LynxOS-178 driver info file	Info file related to DRMLITE driver
drmlite_c5.info	LynxOS-178 driver info file	Info file related to DRMLITE driver
drmlite_c3.info	LynxOS-178 driver info file	Info file related to DRMLITE driver
drmlite_c2.info	LynxOS-178 driver info file	Info file related to DRMLITE driver
app_launcher	Proprietary Collins Aerospace LynxOS-178 User Binary (XCOFF)	Collins Aerospace proprietary binary that executes the application configured in the VCT's PCT file
mkffs	Proprietary Collins Aerospace LynxOS-178 User Binary (XCOFF)	Creates a flash filesystem for the VM
ffsck	Proprietary Collins Aerospace LynxOS-178 User Binary (XCOFF)	Validates the VM's filesystem
arinc615a	Proprietary Collins Aerospace LynxOS-178 User Binary (XCOFF)	ARINC615A data loading functionality
hm_main	Proprietary Collins Aerospace LynxOS-178 User Binary (XCOFF)	Mandatory Health Monitoring/main application running in the privileged VM0

File	Type	Description
<code>afdx_asl_drvr.obj</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	AFDX Avionics System LAN driver
<code>pcie.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	Low-level PCIE communication driver for End-System
<code>norflash.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	NORFLASH driver
<code>iod.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	Flash partitions related driver
<code>touch.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	Touchscreen UART driver
<code>rs422.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	RS422 driver
<code>apm_drvr.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	Aircraft Personality Module driver
<code>rtc.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	Real-Time Clock driver
<code>fat32fs.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	Fat32 Filesystem driver
<code>usb_20rs.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	USB 2.0 driver
<code>ge4.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	Graphics Engine 4 driver
<code>gecko.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	Graphics Engine related driver
<code>merge.dldd</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	Resource Manager driver
<code>ati_drvr.obj</code>	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	ATI RADEON E2400 driver

File	Type	Description
nand_fs_drvr.dldd	Proprietary Collins Aerospace LynxOS-178 Dynamic Loadable Device Driver (XCOFF)	NAND FS driver
drmlite.dldd	Proprietary Collins Aerospace LynxOS-178 User Binary (XCOFF)	Device Resource Manager
pdkm.dldd	Proprietary Collins Aerospace LynxOS-178 User Binary (XCOFF)	Graphics Engine related driver
sda	Proprietary Collins Aerospace LynxOS-178 User Binary (XCOFF)	SDA (Simple Display App - Field Software load/validation)

Approach

The top priority for this research is to ensure the technical accuracy of the claims presented herein.

As a result, IOActive decided that both the firmware and the security issues found would be analyzed, documented, and reported solely based on the disassembled code, without relying on a decompiler's output or an emulator. This avoids an additional layer of uncertainty derived from the use of a specific tool, which eventually might be called into question by the affected entities, as happened previously. This approach also facilitates the independent verification and reproduction of the results in a manner consistent with the scientific method.

This research is based on a static reverse engineering analysis of the exposed files listed in Tables 1 and 2, assisted by the information collected from publicly available materials, such as technical documents, presentations, maintenance manuals, patents, FAA/EASA publications, resumes, and training videos. These sources are referenced throughout the document.

Unfortunately, there is a lack of publicly accessible technical literature comprehensively detailing real-world vulnerabilities affecting either safety-critical avionics or more specifically Lynx178-OS-based deployments. Thus, IOActive believes it is important to document every step of this research as thoroughly as possible, to demonstrate the attack vectors as well as to bring some light into this opaque area of risk.

The AFDR-3700 system has been fully reverse engineered using IDA Pro¹⁵, reconstructing the deterministic network configuration, execution flows and interactions between their different components, identifying the security boundaries, and eventually discovering security vulnerabilities that would allow a malicious actor to compromise the AFDR-3700, thus taking control of the AFD-3700 DUs and its functional applications.

This technical document is intended to comprehensively detail these efforts, such that it can be used to demonstrate the feasibility, validity, and reproducibility of the identified security issues as well as the potential safety impacts.

¹⁵ IDA Pro - <https://hex-rays.com/ida-pro/>

Attack Surface

In the context of an IMA architecture, the focus of this work has been put on finding those attack vectors that would enable either remote or inter-partition exploitation of safety-critical certified avionics during any phase of a flight. Thus, attack vectors requiring physical access through USB or maintenance connectors as well as those depending on an active 'on-ground' discrete signal (see image below) were excluded from the priorities.



Figure 9. Data Loading Capabilities in Pro Line Fusion Suite

This means that data loading attacks were not considered (all data loading needs to be performed while the aircraft is on ground) despite being an otherwise valid attack vector actively evaluated by the aviation industry. The main reason behind this decision is our past experience with Boeing 787 research¹⁶. IOActive discovered a significant number of issues in the ARINC615 and ARINC665 (data loading standards) implementation, but unfortunately, the inherent mitigations for this attack surface were used to discredit that research, regardless of whether they were applicable. It is also worth noting that one of the main

¹⁶ <https://ioactive.com/arm-ida-and-cross-check-reversing-the-787s-core-network/>

arguments employed against that research's conclusions was that the kind of security issues found in non-certified systems would never occur in certified avionics.

Although this research does not cover the data loading attack surface in detail, analysis of the binaries involved¹⁷ revealed that the security posture of the data loading logic implemented in the AFDR-3700 is not any better: it lacks any kind of cryptographically secure logic to validate the integrity and authenticity of the loadable software parts, neither of which are encrypted or signed, thus relying on CRC only.

However, as will be elaborated, the devices and network infrastructure involved in the data loading functionalities (including airborne navigation databases) are actually considered as part of a plausible attack path.

This research was not focused on finding as many issues as possible, as it does not provide any actual value beyond a certain point. Instead, the priority was to find a minimum set of those vulnerabilities and logic issues that allow an attacker to bypass the implemented security boundaries in a safety-critical certified avionics product.

¹⁷ 'sda', 'hm_main' and 'arinc615a'

Impact and Safety Implications

The following section elaborates the approach IOActive followed to demonstrate that the AFD-3700 is a DAL-A device providing actual safety-critical functionalities. This is an important topic in this research, as entities may adduce that the AFD-3700 is certified as a DAL-A merely due to a specific customer request, but actually its functionality is not aligned with a safety-critical certification.

A. FLIGHT DISPLAY SYSTEM

The Rockwell Collins Electronic Flight Instrumentation System (EFIS) consists of an two touchscreen-enabled AFD-3700 Primary Flight Display (PFD) on the pilot's and copilot's panels and a touchscreen-enabled AFD-3700 Multi-Function Display (MFD) located in the center of the panel. Each display includes molded finger grips and may be operated with gloves. Each display is capable of being configured to display information in full screen, half screen and quarter screen windows.

The PFD includes primary attitude, heading, altitude, airspeed, navigation, flight guidance and pilot selectable formats.

Figure 10. King Air 250 Specification¹⁸

As illustrated in Figure 11, the AFD-3700 is authorized according to the TSO-C113a¹⁹, the FAA's Technical Standard Order for airborne multipurpose electronic displays intended for use as an electronic display in the flight deck.



Figure 11. Detail of the AFD-3700 Nameplate

From the requirements that TSO defines, we can highlight the following:

¹⁸ <http://www.africair.com/wp-content/uploads/2016/03/SD-KA250-Unit-250-to-TBD-2015-Oct.pdf>

¹⁹ [http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgTSO.nsf/0/dd968e96d184041e862579f10070b452/\\$FILE/TSO-113a.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgTSO.nsf/0/dd968e96d184041e862579f10070b452/$FILE/TSO-113a.pdf)

a. Functionality. This TSO's standards apply to equipment intended for use as an electronic display in the flight deck by the flight crew in 14 CFR Part 23, 25, 27, and 29 aircraft. This TSO covers basic display standards, but does not include specific application requirements. Specific applications can include flight instrumentation, navigation, engine and system status, alerting, surveillance, communication, terrain awareness, weather, and other displays. This TSO does not provide standards for heads up displays.

b. Failure Condition Classifications. There is no standard minimum failure condition classification for this TSO. The failure condition classification appropriate for the equipment will depend on the intended use of the equipment in a specific aircraft. Document the loss of function and malfunction failure condition classification for which the equipment is designed.

e. Software Qualification. If the article includes software, develop the software according to RTCA, Inc. document RTCA/DO-178B, *Software Considerations in Airborne Systems and Equipment Certification*, dated December 1, 1992 to at least the software level consistent with the failure condition classification defined in paragraph 3.b of this TSO.

Note: The certification liaison process objectives will be considered satisfied after FAA review of the applicable life cycle data.

Figure 12. TSO C113a Requirement Details

An entity applying for the TSO C113a approval would need to define the Failure Condition Classifications as well as the Software Qualification, bearing in mind that both should be consistent with each other. Basically, this means that it should not be reasonable to apply for a TSO C113a approval by stating that a Primary Flight Display is providing the pilots with attitude indication, while its Software Qualification is DO-178B/C DAL-D (a failure will have a minor effect on the aircraft, crew, or passengers).

IOActive does not have access to the Collins safety analysis documents that were shared with the FAA as part of their application for the TSO C113a. However, we can use certain information to confirm that the Software Qualification for the AFD-3700 is DAL-A, which could then be used to infer the Failure Condition Classifications, and vice-versa.

These are the four elements that we will use to perform this task:

- Exposed files
- Resumes (from publicly available websites)
- FAA's Advisor Circular 25-11B
- FAA's Airworthiness Directives

Exposed Files

As illustrated in Figure 7 and Figure 11. Detail of the AFD-3700 Nameplate, the product is certified for DO-178B A/D. Now the task is to demonstrate that the DAL-D certification is not aligned with the main functionality performed by the AFDR-3700, in order to prove the AFDR-3700 is actually DAL-A software.

Based on the analysis of the exposed files, it is possible to determine that the following example applications and file systems²⁰ depend on the integrity of AFDR-3700 to run properly.

Applications:

- ATF-3500 (Advanced Terrain Functions)
- EICAS-6000 (Engine Indication Crew Alerting System) (Figure 14, VCT1648)



Figure 13. EICAS-6000 Showing an Engine Fire Alert²¹

- RTSA-6000 (Radio Tuning Software Application) (Figure 14, VCT409)
- FDSA-6500 (Flight Display System Application) (See Table 1. Exposed files COL_Table01.012)

Airborne Navigation Databases:

- SVS-RWY (Synthetic Vision System - Airport/Runway) (Figure 15, VCT363)
- SVS-OBST (Synthetic Vision System - Obstacles) (Figure 15, VCT1265)
- HRTDB (Terrain Awareness Warning System - High Resolution Terrain Database) (Figure 15, VCT1322)

Filesystems:

- Onboard Maintenance System Application
- Onboard Data Loader Application

²⁰ The functional applications and file systems depend on the integrity of AFDR-3700, so if it is compromised via a VM0 exploit as it is herein described, then it would be possible to take control of them.

²¹ <https://www.youtube.com/watch?v=jwUdYwlyWlw&list=PLMBKNyGwDnjoigp6R5QxtfR9VCHUPI4X1>

- Onboard Maintenance System Tables
- IMA Configuration Index Table (ICIT)

```

////////////////////////////////////
// Virtual Machine Table
////////////////////////////////////

<VM0>                                     // VCT78
GroupIds=;                               // VCT1187
LogicalName=AFDR-3700;                   // VCT1188
CommandLine=/usr/bin/app_launcher;      // VCT1189
EnvironmentVars=HealthMonitorIndex=255
    Field_Load_Id_List = AFDR:IMAT:ICIT:RTSA:EICAS:ECDA:OMSA:ODLA:OMST:ECL-DB:OMSTAR
    PctPathFname=/usr/etc/vm0.pct;       // VCT1190
StdInNodeFname=/dev/null;                // VCT1191
StdOutNodeFname=/dev/null;               // VCT1192
StdErrNodeFname=/dev/null;               // VCT1193
WorkingDir=/;                             // VCT1194
RamFsMount=/tmp;                          // VCT1195
RamFsLim=1048576;                         // VCT1196
RamFsNumOfInodes=24;                     // VCT1197
ActionOnVmErr=0;                          // VCT1198
SysRamMemLim=52428800;                   // VCT1203
PersStorOnLocalLim=512;                  // VCT1206
</VM0>

<VM1>                                     // VCT79
GroupIds=;                               // VCT408
LogicalName=RTSA-6000;                   // VCT409
CommandLine=/usr/bin/app_launcher;      // VCT410
EnvironmentVars=PctPathFname=/mnt/rtsa/rtsa.pct
    HealthMonitorIndex=255;               // VCT411
StdInNodeFname=/dev/null;                // VCT412
StdOutNodeFname=/dev/null;               // VCT413
StdErrNodeFname=/dev/null;               // VCT414
WorkingDir=/mnt/rtsa/;                   // VCT415
RamFsMount=/tmp;                          // VCT416
RamFsLim=0;                              // VCT417
RamFsNumOfInodes=4;                      // VCT418
ActionOnVmErr=3;                         // VCT419
SysRamMemLim=6291456;                     // VCT424
NumOfProcessesLim=10;                    // VCT1218
NumOfThreadsLim=10;                      // VCT846
NumOfTimersLim=4;                        // VCT847
PersStorOnLocalLim=8192;                  // VCT848
FsCacheLim=163840;                       // VCT851
FsCacheAttr=WriteThrough;                 // VCT852
NumOfOpenFdsPerVmlim=256;                // VCT853
NumOfMsgQueuesLim=2;                     // VCT854
NumOfPipesLim=2;                         // VCT855
NumOfSharedMemObjsLim=1;                 // VCT856
NumOfSemaphoresLim=100;                  // VCT857
</VM1>

<VM2>                                     // VCT80
GroupIds=;                               // VCT1647
LogicalName=EICAS-6000;                   // VCT1648
CommandLine=/usr/bin/app_launcher;      // VCT1649
EnvironmentVars=PctPathFname=/mnt/eicas/eicas.pct

```

Figure 14. S1-SL03.vct - AFDR-3700 file showing functional applications

```

<FS2> // VCT502
Mount=/mnt/Apt_Rwy// // VCT363
NumOfInodes=9; // VCT365
MkffsArgs=-F 0; // VCT366
FfsckArgs=-F -r; // VCT367
OwnerId=1; // VCT368
GroupId=1; // VCT369
Permissions=0400; // VCT370
IntegrityAttr=; // VCT371
DataLoadHdrPath=; // VCT372
Size=32; // VCT2502
Chip=1; // VCT2503
</FS2>

<FS3> // VCT503
Mount=/mnt/Obstacles// // VCT1265
NumOfInodes=6; // VCT1267
MkffsArgs=-F 0; // VCT1268
FfsckArgs=-F -r; // VCT1269
OwnerId=1; // VCT1270
GroupId=1; // VCT1271
Permissions=0400; // VCT1272
IntegrityAttr=; // VCT1273
DataLoadHdrPath=; // VCT1274
Size=64; // VCT2504
Chip=1; // VCT2505
</FS3>

<FS4> // VCT1321
Mount=/mnt/atf-svs-config// // VCT1254
NumOfInodes=32; // VCT1256
MkffsArgs=-F 0; // VCT1257
FfsckArgs=-F -r; // VCT1258
OwnerId=1; // VCT1259
GroupId=1; // VCT1260
Permissions=0400; // VCT1261
IntegrityAttr=HardwareNonCritical; // VCT1262
DataLoadHdrPath=/mnt/atf-svs-config// // VCT1263
Size=32; // VCT2506
Chip=0; // VCT2507
</FS4>


<FS5> // VCT1322
Mount=/mnt/atf-hi-resolution-terrain// // VCT1243
NumOfInodes=1000; // VCT1245
MkffsArgs=-F 0; // VCT1246
FfsckArgs=-F -r; // VCT1247
OwnerId=1; // VCT1248
GroupId=1; // VCT1249
Permissions=0400; // VCT1250
IntegrityAttr=; // VCT1251
DataLoadHdrPath=; // VCT1252
Size=3776; // VCT2508
Chip=1; // VCT2509
</FS5>

```

Figure 15. S1-SL04.vct – Mounted filesystems

Resumes

The following extracts from the publicly available resumes of Collins' engineers provide a clear indication that the EFIS project, and thus the AFDR-3700, in the Pro Line Fusion product line is being developed following DAL-A standards (core applications such as EICAS or FDSA may be certified as DAL-B or above)



Rockwell Collins
5 yrs
Hyderabad Area, India


- **Senior Engineer**
Aug 2014 - Jun 2015 - 11 mos
- **Engineer**
Aug 2012 - Jul 2014 - 2 yrs
Projects: Bombardier CSeries, Gulfstream G280, Bombardier M145, Embraer Executive Jet EEJ, Embedded Display System EDS:
 - Electronic Flight Instrument System (EFIS):
These projects are related to Display Systems and come under Electronic Flight Instrument System (EFIS).
I was involved in verification of software component in Electronic Flight Instrument System. The purpose of verification is to verify the compliance of the software to DO-178B standards (Level A). The verification includes Requirement Based Test Coverage Analysis, Structural Coverage Analysis and Traceability Analysis. The verification will primarily be via implementation and execution of Test Procedures/Scripts in qualified tools. Software Software Integration Testing(SSIT) is performed for the verification activities and Structural Coverage Analysis Reports are generated.

Actively involved in:

- Writing of Test Cases and Test Procedures in Python and XML corresponding to the requirements.
- Using MATLAB to verify requirements against the model.
- Generate the Structural Coverage Analysis Report corresponding to the Test Procedure/Scripts so as to verify the compliance with DO-178B standards (Level A).

Performing Peer Reviews for the Test Case, Test Procedures, Test Results and Structural Coverage Reports.

Figure 16. Resume of Engineer #1



Software Engineer
Rockwell Collins
Aug 2010 - Present - 11 yrs 7 mos
Cedar Rapids, Iowa Area

- Two years of experience as a software and system development, verification and validation engineer
- Verifying EFIS software for Embraer Legacy 450/500(EEJ) Pro Line Fusion® Avionics Suite using DO-178B Level A Standards
 - Test correct functionality and establish conditions that reveal potential errors
 - Task includes interpreting FDSA software requirements, capturing test cases in DOORs, writing automated/visual test procedures in python or xml, verifying and/or analyzing code for missing coverage, reviewing test cases and test procedures for correct implementation and compliance to standards.
- Developed test procedures to verify system requirements using ARP4754A (2012)
Aircrafts Supported: Bombardier CSeries/Learjet 85, Mitsubishi Regional Jet (MRJ), Embraer Legacy 450/500 (EEJ)
 - Served as the domain focal for FDSA
 - Designed test procedures which are ran on standalone cockpit rigs and/or test stations for verification
- Developed EFIS software for Pro Line Fusion® Avionics Suite using DO-178B Level A Standards
Aircrafts Supported: Bombardier Global Express XRS/Global 5000/CSeries, MRJ, Gulfstream G250 and EEJ

Figure 17. Resume of Engineer #2

FAA's Advisor Circular 25-11B

The FAA's Advisor Circular 25-11B provides a guidance for design, integration, installation approval of electronic flight deck displays²², which will be used to check the consistency between the safety assessment required by the Software Failure Conditions and the Software Qualification.

The following examples on the hazard classification level can be linked directly to some of the scenarios that can be achieved by compromising the AFDR-3700 (see Figure 90. Scenario for a Compromised AFDR-3700) which provide the malicious actor the ability to maliciously influence the functional applications (e.g. EICAS and FDSA) that depend on it. At this point we should recall that catastrophic failures in the Failure Condition Classifications would require a DAL-A Software Qualification to be consistent.

Table 4-1. Example Safety Objectives for Attitude Failure Conditions		
Failure Condition	Hazard Classification	Qualitative Probability
Loss of all attitude displays, including standby display	Catastrophic	Extremely Improbable
Loss of all primary attitude displays	Major – Hazardous ¹	Remote – Extremely Remote ¹
Display of misleading attitude information on both primary displays	Catastrophic	Extremely Improbable

Figure 18. Hazard Classification Level for Display of Misleading Attitude Information

Table 4-7. Example Safety Objectives for Engine Failure Conditions		
Failure Condition	Hazard Classification	Qualitative Probability
Loss of one or more required engine indications for a single engine	Major	Remote
Misleading display of one or more required engine indications for a single engine	Major	Remote
Loss of one or more required engine indications for more than one engine	Hazardous	Extremely Remote ¹
Misleading display of any required engine indications for more than one engine	Catastrophic	Extremely Improbable ²

Figure 19. Hazard Classification Level for Display of Misleading Engine Information

²² https://www.faa.gov/documentlibrary/media/advisory_circular/ac_25-11b.pdf

The following point in the guidance relates to a Windowing architecture.

- 4.6.9 For those systems that integrate windowing architecture into the display system, a means should be provided to control the information shown on the displays, such that the integrity of the display system as a whole will not be adversely impacted by anomalies in the functions being integrated. This means of controlling the display of information, called window manager in this AC, should be developed to the software assurance level at least as high as the highest integrity function of any window. For example, a window manager should be level “A” if the information displayed in any window is level “A” (see RTCA DO-178C, *Software Considerations in Airborne Systems and Equipment Certification*). SAE ARP4754A, *Guidelines for Development of Civil Aircraft Systems*, provides a recommended practice for system development assurance.

Figure 20 25-11B guidance

We can directly match the point above with the resume in Figure 21, where the DS6000 Window Manager application is developed under the DAL-A standard, meaning that at least one of the windows contains DAL-A data.

Senior Software Engineer

Jan 2010 - Oct 2013 · 3 yrs 10 mos

•Commercial: Displays Applications Department

•Project: DS6000 Window Manager / Nav Master (DWM/NM) Applications for Proline Fusion (DO-178 Level A)

•Lead Developer and Architect for Pro Line Fusion Navigation Master Applications (Model Based Development)

•Defined high and low level requirements and provided linking to implementation using DOORS for DWM and NM

•Develop DWM/NM software both logical and graphical using ARINC 661, Matlab/Simulink and VAPS XT 661

•Peer reviews DWM/NM software implementation and code review

•Support SOI audits by providing thread analysis and overview of peer review history

•Support DWM/NM Verification team including coverage analysis using LDRA

•Helped setup working relationship with Rockwell's new offsite India Design Center (IDC) by traveling to Hyderabad, India in July 2010

•Train new DWM/NM engineers

Figure 21 Resume from Engineer #3

VAPS XT²³ is a safety-critical DO-178B/C DAL-A HMI for avionics systems, which is being used as part of the development of functional applications for the Pro Line Fusion DUs.

²³ <https://www.presagis.com/en/product/vaps-xt/>

FAA's Airworthiness Directives

It was also possible to confirm that the AFD-3700 sustains safety-critical functionality by consulting the Airworthiness Directive database published by the FAA:

1. A potential failure in the ASIC of the AFD-3010 (a previous version of the AFD-3700) required the release of an Airworthiness Directive²⁴ (AD) in 2002.

Summary	This amendment adopts a new airworthiness directive (AD) that applies to certain Rockwell Collins, Inc. (Rockwell Collins) AFD-3010 adaptive flight display units that are installed on aircraft. This AD requires you to inspect the AFD-3010 unit to determine if it contains an MFP386 Application Specific Integrated Circuit (ASIC) device with a date code of 0128. This AD also requires you to have any AFD-3010 units with an MFP386 device with a date code of 0128 modified. This AD is the result of reports of a manufacturing defect. The actions specified by this AD are intended to prevent premature failure of the ASIC, which could result in the AFD-3010 unit displaying erroneous primary flight and engine parameter information. Such failure could lead to the pilot using incorrect information when making critical flight safety decisions.
----------------	--

Figure 22. Summary of the AD for the AFD-3010

2. A potential failure in the FDSA-6500 functional application (One of the applications depending on the AFDR-3700, see Table 1. Exposed files) required the release of an AD²⁵ from the FAA/EASA in 2019, to address an “unsafe condition.”


SUMMARY:
 The FAA is superseding Airworthiness Directive (AD) AD 2019-12-09 for certain Rockwell Collins, Inc. (Rockwell Collins) FDSA-6500 flight display system applications installed on airplanes. AD 2019-12-09 imposed operating limitations on the traffic collision avoidance system (TCAS). AD 2019-12-09 was prompted by conflict between the TCAS display indications and aural alerts that may occur during a resolution advisory (RA) scenario. This AD retains the requirements of AD 2019-12-09 until a software upgrade is completed. The FAA is issuing this AD to address the unsafe condition on these products.

Figure 23. Summary of the AD for the FDSA-6500

²⁴ <https://www.govinfo.gov/app/details/FR-2002-10-16/02-25717/summary>

²⁵ <https://www.federalregister.gov/documents/2021/03/25/2021-06156/airworthiness-directives-rockwell-collins-inc-flight-display-system-application>

This AD provides a clear description of the safety problem:

(e) Unsafe Condition

This AD was prompted by a conflict between the traffic collision avoidance system (TCAS) primary display indications and aural alerts during a resolution advisory (RA) scenario. The FAA is issuing this AD to prevent conflicting TCAS information, which could result in the pilot under-correcting or over-correcting and may lead to inadequate aircraft separation and a mid-air collision.

Figure 24 Unsafe Condition description

Obviously, this kind of catastrophic error can only be caused by a failure of a DAL-A software, assuming there is no single point of failure in safety-critical avionics.

Thus, it is reasonable to assume our initial premise of the AFDR-3700 being an actual DAL-A sustaining safety-critical functionality is correct, as we have that:

- The FDSA-6500 is a DAL-A application, managed by a DAL-A Window Manager, running in a DAL-A device.
- The DAL-A FDSA-6500 functional application can only rely on a DAL-A AFDR-3700 according to the “Rely-Guarantee” model, used in certification of modular systems. This means that application X (FDSA-6500) is guaranteed to access the resources provided by system Y (in this case the AFDR-3700). This must be true, otherwise it could not be certified as application X (DAL-A) would be relying on a system Y that is certified using a lower level (such as DAL-D). That situation does not guarantee the proper functioning of application X, which breaks the model.

Also, the AFD-3700 DUs are generally part of the Master Minimum Equipment List (MMEL) of a Pro Line Fusion-equipped aircraft.

U.S. DEPARTMENT OF TRANSPORTATION				MASTER MINIMUM EQUIPMENT LIST			
FEDERAL AVIATION ADMINISTRATION							
AIRCRAFT: Textron Aviation Model 300			REVISION NO. 10 DATE: 04/27/2018			PAGE NO. 34-5	
MMEL TABLE KEY							
SYSTEM & SEQUENCE NO.	ITEM	1. REPAIR CATEGORY					
		2. NUMBER INSTALLED					
		3. NUMBER REQUIRED FOR DISPATCH					
		4. REMARKS OR EXCEPTIONS					
34. NAVIGATION							
Sequence No.	Item	1	2	3	4	Change Bar	
-25-02	Adaptive Flight Display System (AFD) (Collins Pro Line Fusion Equipped Airplanes)						
-01	Single Pilot (PFD 2 Control, PFD 2 Fan Inop, PFD Fan 1 Inop messages)	B	3	2	May be inoperative provided PFD 1 and the MFD are operative		
-02	Dual Pilot (MFD Control, MFD Fan Inop messages)	B	3	2	May be inoperative provided PFD 1 and PFD 2 are operative.		

Figure 25 MMEL Textron Aviation Model 300²⁶

Potentially Affected Aircraft

Based on reputable publicly available information, the list of those aircraft potentially equipped with the impacted version of the Pro Line Fusion suite²⁷ may include, but is not limited to:

- Embraer Legacy 450/500²⁸ (Business)
- Gulfstream G280²⁹ (Business)
- Bombardier Global 5000/6000³⁰ (Business)
- Bombardier Challenger 604³¹ (Business)

²⁶ https://fsims.faa.gov/wdocs/mmel/be-300_rev_10.pdf

²⁷ It does not mean all these aircraft are vulnerable. This requires to be evaluated on a case-by-case basis.

²⁸ <https://www.collinsaerospace.com/what-we-do/Business-Aviation/Flight-Deck/Pro-Line-Fusion/Embraer-Legacy-450-500>

²⁹ <https://www.collinsaerospace.com/what-we-do/Business-Aviation/Flight-Deck/Pro-Line-Fusion/Gulfstream-G280-With-Pro-Line-Fusion-And-HGS>

³⁰ <https://www.collinsaerospace.com/what-we-do/Business-Aviation/Flight-Deck/Pro-Line-Fusion/Pro-Line-Fusion-For-Bombardier-Global-5000-6000>

³¹ <https://www.collinsaerospace.com/what-we-do/Business-Aviation/Platforms/Bombardier/Challenger-604/Avionics>

-
- Beechcraft King Air³² (Military/Business)
 - Cessna Citation CJ1+, CJ2+, and CJ3³³ (Business)
 - Viking Air CL-125T, CL-415³⁴ (Firefighting)
 - Embraer KC-390³⁵ (Military)

IOActive selected reputable, published sources for the above information such as company websites to compile this list, we recognize not all reputable sources are created accurate or remain accurate as time progresses.

Disputed statement 1

A pre-publication version of the paper shared with Collins Aerospace contained a list of affected aircraft, based on publicly available information.

Collins Aerospace explicitly communicated to IOActive in a letter dated April 7, 2022 that:

- The list was incorrect.
- A corrected list of the affected aircraft will not be provided as it is not necessary to support the research.

IOActive considers that this information is certainly necessary to support the research, as it provides a valuable information about its impact.

That original list included certain commercial and military Airbus models, which have been removed from this current list, according to some consistent information received from different sources.

If any additional information is received, that clearly demonstrates this list is still incorrect, IOActive will proceed to update the paper accordingly, also publicly rectifying if required.

³² <https://www.collinsaerospace.com/what-we-do/Business-Aviation/Flight-Deck/Pro-Line-Fusion/Pro-Line-Fusion-Upgrade-For-Beechcraft-King-Air>

³³ <https://www.collinsaerospace.com/what-we-do/Business-Aviation/Flight-Deck/Pro-Line-Fusion/Pro-Line-Fusion-Upgrade-For-Citation-Cj3>

³⁴ <https://www.ainonline.com/aviation-news/business-aviation/2019-03-19/viking-launches-avionics-upgrade-its-fire-bombers>

³⁵ <https://www.collinsaerospace.com/-/media/project/collinsaerospace/collinsaerospace-website/product-assets/marketing/k/kc-390-brochure-0711.pdf?rev=787c1c35ebdd4cbebb2365fdd748b686>

Technical Analysis

Reverse Engineering Notes

The KDI (COL_Application01.001) contains a symbol table where each entry is 0x12 bytes (see Figure 27). The first 8 bytes hold the symbol name followed by its address. If the symbol name length is longer than 8 bytes, the first 4 bytes are then NULL and the next 4 bytes contain an offset into an array of strings where the symbol name can be resolved (see Figure 26).

For the remaining binaries (XCOFF), the symbols and debug information were found in VM0's hm_main as well as in most of the drivers.




Figure 26. Kernel Symbol Table Structure

	Symbol Name	Address	
0	2E73 7461 7274 0000	B001 0020	0001 0000 0200 .start ∞
18	2E67 6574 5F74 6561	B001 0288	0001 0000 0200 .get_tea ∞ à
36	2E73 6574 5F74 6F63	B001 0290	0001 0000 0200 .set_toc ∞ è
54	0000 0000 0000 0004	B001 0298	0001 0000 0200 ∞ ò
72	7374 6172 7400 0000	B010 5280	0002 0000 0200 start ∞ RÄ
90	6765 745F 7465 6100	B010 5290	0002 0000 0200 get_tea ∞ Rê
108	7365 745F 746F 6300	B010 52A0	0002 0000 0200 set_toc ∞ R†
126	0000 0000 0000 0013	B010 52B0	0002 0000 0200 ∞ R∞
144	2E72 6B5F 626F 6F74	B001 0760	0001 0020 0200 .rk_boot ∞ `
162	524F 4D6B 0000 0000	B010 0000	0002 0000 0200 ROMk ∞
180	524F 4D6B 7000 0000	B010 00C4	0002 0000 0200 ROMkp ∞ f
198	726B 5F62 6F6F 7400	B010 5320	0002 0000 0200 rk_boot ∞ S
216	2E6C 6F77 496E 6974	B001 1000	.lowInit ∞

Figure 27. Detail of Kernel Symbol Table

It was possible to infer the PowerPC family through one of the CPU Support Package (CSP) functions in the kernel (see Figure 28).

```

ROM:00050510
ROM:00050510      .csp_pre_init:                # CODE XREF: .lowInit+90fp
ROM:00050510                                     # DATA XREF: ROM:001031984o
ROM:00050510
ROM:00050510      .set sender_sp, -0x48
ROM:00050510      .set var_C, -0xC
ROM:00050510      .set var_8, -8
ROM:00050510      .set var_4, -4
ROM:00050510      .set sender_lr, 8
ROM:00050510
ROM:00050510 7C 08 02 A6      mflr      r0
ROM:00050510 93 A1 FF F4      stw      r29, var_C(r1)
ROM:00050510 93 C1 FF F8      stw      r30, var_8(r1)
ROM:00050510 93 E1 FF FC      stw      r31, var_4(r1)
ROM:00050520 90 01 00 08      stw      r0, sender_lr(r1)
ROM:00050520 94 21 FF B8      stwu     r1, sender_sp(r1)
ROM:00050520 7C 7E 1B 78      mr       r30, r3
ROM:00050520 83 FE 00 24      lwz      r31, 0x24(r30)
ROM:00050530 48 00 3B A1      bl       .csp_read_cpuversion
ROM:00050530 4F FF FB 82      crmove   4*cr7+so, 4*cr7+so
ROM:00050530 90 7E 00 04      stw      r3, 4(r30)
ROM:00050530 80 1E 00 04      lwz      r0, 4(r30)
ROM:00050540 2C 00 13 02      cmpwi    r0, 0x1302
ROM:00050540 40 82 00 10      bne      loc_00050554
ROM:00050540 88 1F 00 0C      lbz      r0, 0xC(r31)
ROM:00050540 60 00 00 80      ori      r0, r0, 0x80
ROM:00050550 98 1F 00 0C      stb      r0, 0xC(r31)
ROM:00050554
ROM:00050554      loc_00050554:                # CODE
ROM:00050554 83 BE 00 0C      lwz      r29, 0xC(r30)
ROM:00050558 3B BD 0F FF      addi     r29, r29, 0xFFFF
ROM:00050558      .csp_read_cpuversion:
ROM:00050558      mfpvr    r3
ROM:00050558      srwi     r3, r3, 16
ROM:00050558      blr

```

Figure 28. Kernel `csp_pre_init` Function

At 0xB0050540 the CPU ID 0x1302 indicates an AMCC PowerPC 440EP. This is also corroborated by the register values used during the initialization of the on-chip Ethernet MAC controller in the `pcie.ldd` driver, which corresponds to the PowerPC 4XX family.

Attacking a LynxOS-178-based System

What is LynxOS-178?

LynxOS-178 is Lynx Software Technologies Inc.'s Real-Time Operating System (RTOS) for safety-critical systems. Lynx Software Technologies, Inc. is the premier developer of POSIX conformant real-time operating systems. Our flagship product, called LynxOS, is in use in hundreds of thousands of installations where high reliability and hard real-time determinism are essential. LynxOS-178 is based on LynxOS and has the features necessary for safety-critical applications such as aviation, defense, medicine, along with other business-critical fields. Along with the operating system and the development tools, Lynx Software Technologies can optionally provide the necessary artifacts to permit LynxOS-178 to be used in systems that are certifiable up to level A of the RTCA DO-178C standard. In addition, LynxOS-178 provides the ability to run multiple levels of DO-178C criticality on the same platform.

Figure 29. LynxOS-178 Description (Extracted from LynxOS-178 documents³⁶ Found at GitHub)

From a functional and security perspective, a LynxOS-178 target is more similar to any modern desktop OS than the usual RTOS found in most Common-Off-The-Shelf (COTS) embedded devices (see Figure 29).




Figure 30. LynxOS-178 Architecture (Extracted from Leaked LynxOS-178 Documents³⁶)

³⁶ https://github.com/blackqbit/lynxos-178_arm_docs/blob/main/2203-00_los178_ig.pdf

It is highly recommended to review the documents referenced in Figure 30 to get a complete understanding of the LynxOS-178 environment. At a high level, there are four important concepts that need to be briefly introduced to provide the required context:

1. VCT files

Virtual Machine Configuration Table

The Virtual Machine Configuration Table (VCT) is a file that contains configuration information for the target system running LynxOS-178. The contents of the VCT should be thought of as a well-defined set of descriptors that configures the LynxOS-178 Operating System. It supports the ability to create partitions (also known as virtual machines (VMs)) and configure each partition to match its design as determined by the user.

Figure 31. VCT Definition

It is important to clarify that despite the naming conventions, LynxOS-178 is not a hypervisor. The VM concept in this context is similar to the process concept in any modern desktop OS: neither memory nor resources are shared between the VMs. From now on, the VM term will be used according to the LynxOS-178 specification.

2. VM0

VM0 is a unique VM with special privileges. These privileges are similar to the root privileges in a UNIX system. For example, VM0 can override protections set in other VMs and can reboot the computer. In addition, VM0 monitors the state of the processes and threads contained within the other VMs. This is crucial to understand the implications of this research because we are exploiting an application running in VM0, so a successful attack leads to complete control over the AFD-3700 system, as will be elaborated in the coming sections.

3. Inter-Partition Mechanisms

As defined by ARINC-653 inter-partition communication (communication between VMs) is based on message passing through message ports. These messages are exchanged through channels, which are a logical link between a source VM and one or more destination VM. In the context of the LynxOS-178, the different VMs can send and receive messages through multiple channels via defined access points, called ports (queuing or sampling).

The standard does not define the underlying transport mechanism, so it is transparent to the applications, allowing ARINC 653 applications to communicate in the same way regardless of whether they run on the same shared computing resource or even across an AFDX avionics network. These communication flows are fully deterministic and are statically defined as part of the system configuration process.

The analysis of this implementation (developed by Collins Aerospace), including its configuration, has been a core part of this research as it helped to demonstrate the plausible attack paths.

4. Avionics System LAN

A Pro Line Fusion-equipped aircraft may be considered an e-Enabled aircraft, thus presenting certain functional similarities to other e-Enabled aircraft, such as the Boeing 787 or an Airbus A380. In this case, the AFDX network implemented by Collins Aerospace is called the 'Avionics System LAN.' In this network we can find the usual components, such as AFDX switches, data concentrators (IOC) and data loaders, as well as the AFD-3700 as obviously.

Security Boundaries

In order to bypass the security boundaries implemented in the AFDR-3700 we are required to uncover vulnerabilities that enable executing arbitrary code in a privileged domain, either VM0's main app or kernel/drivers, coming from a less privileged partition (VM) or even remotely, through the Avionics System LAN.

In general terms, the ability to compromise a non-certified partition running DAL D/E applications (i.e. In-Flight Entertainment Systems) should be assumed. For the B/C levels, this task may be more difficult as the code requires additional certification requirements.

AFDR-3700 Boot Sequence

Kernel	CINIT	VM0	app_launcher	hm_main
		VM1	app_launcher	Functional App 1
		VM_n	app_launcher	Functional App n

Figure 32. Regular Boot Sequence in AFD-3700

The boot sequence depicted in Figure 32 may vary according to the boot mode (AFDR-3700 defines six different boot modes described below) and its corresponding VCT, but the AFDR-3700 implements a common approach to launch the required VM applications.

`App_launcher` is the main binary that runs by default for any VM defined in the VCT file. Actually, this binary is in charge of parsing the Collins Aerospace's `Process Configuration Table` file referenced by `PctPathFName` (only `vm0.pct` was present in the leaked files) and launching the corresponding application defined in it. This PCT file format is not documented, so it is considered a custom part added by Collins Aerospace to the VCT logic.


```

1 //////////////////////////////////////////////////
2 // Virtual Machine Configuration Table
3 //
4 // File Name: S1-SL03.VCT
5 // Generated By: jafllore9
6 // Generated On: 07 May 2014 18:45:55
7 //
8 // CRs Implemented: FUSN00400510,
9 //
10 // (C)2014 Rockwell Collins. All rights reserved.
11 //
12 //////////////////////////////////////////////////
13
14
15 //////////////////////////////////////////////////
16 // Scalar Sub Table
17 //////////////////////////////////////////////////
18
19 VctCrc=; // VCT2677
20 VctCpn=; // VCT161
21 VctVersion=150; // VCT162
22 NumOfVms=6; // VCT163
23 NumOfDdds=3; // VCT164
24 NumOfFs=19; // VCT165
25 ActionOnModuleErr=3; // VCT166
26 IbitDuration=0; // VCT171
27 NetworkInterface=Winsock2.2; // VCT173
28 ColdStartSchedule=; // VCT174
29 ColdStartDuration=0; // VCT175
30 RunTimeSchedule=0[1] 1[3] 2[7] 3[12] 5[2] 0[2] 1[2] 2[8] 3[11] 5[2]; // VCT178
31
32 //////////////////////////////////////////////////
33 // Virtual Machine Table
34 //////////////////////////////////////////////////
35
36 <VM0> // VCT78
37 GroupIds=; // VCT1187
38 LogicalName=AFDR-3700; // VCT1188
39 CommandLine=/usr/bin/app_launcher; // VCT1189
40 EnvironmentVars=HealthMonitorIndex=255
41     Field_Load_Id_List = AFDR:IMAT:ICIT:RTSA:EICAS:ECDA:OMSA:ODLA:OMST:ECL-DB:OMSTAR
42     PctPathFname=/usr/etc/vm0.pct; // VCT1190
43 StdInNodeFname=/dev/null; // VCT1191
44 StdOutNodeFname=/dev/null; // VCT1192
45 StdErrNodeFname=/dev/null; // VCT1193
46 WorkingDir=/; // VCT1194
47 RamFsMount=/tmp; // VCT1195
48 RamFsLim=1048576; // VCT1196
49 RamFsNumOfInodes=24; // VCT1197
50 ActionOnVmErr=0; // VCT1198
51 SysRamMemLim=52428800; // VCT1203
52 PersStorOnLocalLim=512; // VCT1206
53 </VM0>

```

Figure 33. S1-SL03.vct

In Figure 33 at line 42, we can see the reference to the `vm0.pct` file, which `app_launcher` has to parse in order to know the process that needs to be launched.

```

52991 // PCT file for 460 EDS board to run hm_main in vm0.
52992 // File: vm0.pct
52993 // Note: PctCrc can not be left blank
52994 PctCrc = 0x87E5DB9A;
52995 ///////////////////////////////////////////////////////////////////
52996 // PE0 - ApplicationX
52997 // PExx where xx is the sequential numbering (0, 1, 2) of the process.
52998 // Leading zeroes are suppressed.
52999 ///////////////////////////////////////////////////////////////////
53000 <PE0> // Start of Application Process 0 Table.
53001 // Process specific information
53002 CommandLine=/usr/bin/hm_main;
53003
53004 EnvironmentVars=; //Just use VCT settings
53005
53006 // Device nodes to use for standard I/O streams.
53007 StdInNodeFname=/dev/null;
53008 StdOutNodeFname=/dev/rs232A_nonblocking;
53009 StdErrNodeFname=/dev/rs232A_nonblocking;
53010
53011 // File systems info
53012 WorkingDir=/; // Home Directory
53013 // Process priority. It doesn't matter since hm_main sets it's own priority
53014 Priority=80;
53015 </PE0> // End of Application Process 0

```

Figure 34. vm0.pct

As shown in Figure 34, the vm0.pct file contains the reference to the binary implementing the functional application that should be running in that specific VM, in this case hm_main for VM0.

AFD-3700 Health Monitor Application: hm_main

This is a Collins Aerospace's application which implements part of the Health Monitoring logic mandated by the ARINC 653 standard. In addition, it is the core user-mode application in the AFD-3700 as it initializes, supervises, and controls key functionalities of the DU. Essentially, the AFD-3700 cannot run properly without a fully working hm_main application.

As previously mentioned, the VM0 partition is, by default, a privileged partition within the LynxOS-178 architecture. From a security perspective, this has several implications. By exploiting the hm_main application, we would gain control over key functionalities that can be used to fully compromise the entire LynxOS-178 deployment. For instance, once the ability to execute code in hm_main has been achieved, it is possible to directly load an arbitrary driver via the dr_install (see Figure 35) syscall, which requires the VM0's UID.

```

ROM:B0026D00      .dr_install:                                # DATA XREF: ROM:dr_install4o
ROM:B0026D00
ROM:B0026D00      .set sender_sp, -0x60
ROM:B0026D00      .set saved_toC, -0x4C
ROM:B0026D00      .set var_28, -0x28
ROM:B0026D00      .set var_24, -0x24
ROM:B0026D00      .set var_1C, -0x1C
ROM:B0026D00      .set var_18, -0x18
ROM:B0026D00      .set var_14, -0x14
ROM:B0026D00      .set var_10, -0x10
ROM:B0026D00      .set var_C, -0xC
ROM:B0026D00      .set var_8, -8
ROM:B0026D00      .set var_4, -4
ROM:B0026D00      .set sender_lr, 8
ROM:B0026D00
ROM:B0026D00 7C 08 02 A6      mflr      r0
ROM:B0026D04 93 21 FF E4      stw      r25, var_1C(r1)
ROM:B0026D08 93 41 FF E8      stw      r26, var_18(r1)
ROM:B0026D0C 93 61 FF EC      stw      r27, var_14(r1)
ROM:B0026D10 93 81 FF F0      stw      r28, var_10(r1)
ROM:B0026D14 93 A1 FF F4      stw      r29, var_C(r1)
ROM:B0026D18 93 C1 FF F8      stw      r30, var_8(r1)
ROM:B0026D1C 93 E1 FF FC      stw      r31, var_4(r1)
ROM:B0026D20 90 01 00 08      stw      r0, sender_lr(r1)
ROM:B0026D24 94 21 FF A0      stwu     r1, sender_sp(r1)
ROM:B0026D28 7C 7A 1B 78      mr       r26, r3
ROM:B0026D2C 81 22 00 18      lwz      r9, 0x18(r2)
ROM:B0026D30 81 29 00 00      lwz      r9, 0(r9)
ROM:B0026D34 A3 89 00 74      lhz      r28, 0x74(r9)
ROM:B0026D38 2C 1C 00 00      cmpwi    r28, 0      # UID == 0?
ROM:B0026D3C 41 82 00 0C      beq      loc_B0026D48
ROM:B0026D40 38 60 00 01      li       r3, 1
ROM:B0026D44 48 00 01 70      b        loc_B0026EB4

...

ROM:B0026E0C      loc_B0026E0C:                                # CODE XREF: .dr_install+1041j
ROM:B0026E0C 80 7A 00 00      lwz      r3, 0(r26)   # 1st parameter - path to driver file
ROM:B0026E10 38 80 00 00      li       r4, 0
ROM:B0026E14 4B FF A8 69      bl       .file_open
ROM:B0026E18 4F FF FB 82      crmove   4*cr7+so, 4*cr7+so
ROM:B0026E1C 7C 7F 1B 79      mr       r31, r3

...

ROM:B0026EFC 7F E3 FB 78      mr       r3, r31
ROM:B0026F00 7F C4 F3 78      mr       r4, r30
ROM:B0026F04 7F A5 EB 78      mr       r5, r29
ROM:B0026F08 48 02 D7 D9      bl       .load_module_xcoeff

```

Figure 35. *dr_install* Partial Implementation

Vulnerable SNMP Daemon in `hm_main`

With this information in mind, it seems clear that `hm_main` is a top priority. The initial analysis of the binary revealed a `snmpd` daemon, which was found to be vulnerable (see Figure 36) to a previously unknown vulnerability.

Curiously, this `snmpd` implementation is based on the code³⁷ provided in “TCP/IP Illustrated Volume 2 – the Implementation³⁸.” Although the PowerPC assembly presented herein partially matches the original code, some modifications have been added by Collins Aerospace developers; for instance, a bounds check in `.alreadlen`, which receives an additional parameter in comparison to the original implementation. Also, the dynamic memory allocated for the linked list in the original code has been moved to the stack³⁹ in the `hm_main` implementation. Finally, some fields in the internal structures have been removed.

This SNMP implementation is prone to, at least⁴⁰, a stack-based buffer overflow due to a lack of bounds checking in the `alreadoid` function while parsing Object Identifiers (OIDs).

³⁷ <https://cis.temple.edu/~ingargio/cis307/software/TCPIP-vol2/snmp/>

³⁸ https://en.wikipedia.org/wiki/TCP/IP_Illustrated

³⁹ Memory is statically allocated due to LynxOS-178 VMs deterministic constraints

⁴⁰ There are additional vulnerable paths that have not been elaborated in this paper.

Snmpd invokes `snmp_poll_request` to receive SNMP requests through `snmp_sock_recv`, which limits the size of the packet to 0x59C bytes (see 0x10012084 in Figure 36 and MTU values at Figure 78. Rx Configuration Index Table and Rx Configuration Table). The received packet is parsed by `snparse` and eventually transformed to an internal format by `sna2b`.

```
.text:10012044                                .globl .snmp_poll_requests
.text:10012044                                .snmp_poll_requests:                # CODE XREF: .snmpd+B4;p
.text:10012044                                .set sender_sp, -0x1848
.text:10012044                                .set var_1810, -0x1810
.text:10012044                                .set var_1800, -0x1800
.text:10012044                                .set var_1260, -0x1260
.text:10012044                                .set var_CC0, -0xCC0
.text:10012044                                .set var_CB0, -0xCB0
.text:10012044                                .set var_CA9, -0xCA9
.text:10012044                                .set var_CA8, -0xCA8
.text:10012044                                .set var_CA4, -0xCA4
.text:10012044                                .set var_CA0, -0xCA0
.text:10012044                                .set var_C9C, -0xC9C
.text:10012044                                .set var_C90, -0xC90
.text:10012044                                .set var_10, -0x10
.text:10012044                                .set var_C, -0xC
.text:10012044                                .set var_8, -8
.text:10012044                                .set var_4, -4
.text:10012044                                .set sender_lr, 8
.text:10012044                                mflr                                r0
.text:10012048                                stw                                r28, var_10(r1)
.text:1001204C                                stw                                r29, var_C(r1)
.text:10012050                                stw                                r30, var_8(r1)
.text:10012054                                stw                                r31, var_4(r1)
.text:10012058                                stw                                r0, sender_lr(r1)
.text:1001205C                                stwu                               r1, sender_sp(r1)
.text:10012060                                mr                                r28, r3
.text:10012064                                addi                               r3, r1, 0x1848+var_C90
.text:10012068                                stw                                r3, 0x1848+var_C9C(r1)
.text:1001206C                                li                                r4, 0x14
.text:10012070                                bl                                .link_bindings
.text:10012074                                crmove                             4*cr7+so, 4*cr7+so
.text:10012078                                addi                               r30, r1, 0x1848+var_1800
.text:1001207C                                mr                                r3, r28
.text:10012080                                mr                                r4, r30
.text:10012084                                li                                r5, 0x59C
.text:10012088                                addi                               r6, r1, 0x1848+var_1810
.text:1001208C                                bl                                .snmp_sock_recv
.text:10012090                                crmove                             4*cr7+so, 4*cr7+so
.text:10012094                                mr                                r29, r3
.text:10012098                                ble                               loc_10012230
.text:1001209C                                lwz                               r9, in_packets_TC # _snmpd.bss_c
.text:100120A0                                lwz                               r11, 0(r9)
.text:100120A4                                addi                               r11, r11, 1
.text:100120A8                                stw                                r11, 0(r9)
.text:100120AC                                addi                               r31, r1, 0x1848+var_CC0
.text:100120B0                                mr                                r3, r31
.text:100120B4                                mr                                r4, r30
.text:100120B8                                mr                                r5, r29
.text:100120BC                                bl                                .snparse
.text:100120C0                                crmove                             4*cr7+so, 4*cr7+so
.text:100120C4                                cmpwi                             r3, -1
.text:100120C8                                beq                               loc_10012230
.text:100120CC                                mr                                r3, r31
.text:100120D0                                bl                                .sna2b
.text:100120D4                                crmove                             4*cr7+so, 4*cr7+so
.text:100120D8                                cmpwi                             r3, -1
.text:100120DC                                bne                               loc_100120F4
.text:100120E0                                lwz                               r11, asn_parse_error_TC # 0x2000F3D8
.text:100120E4                                lwz                               r9, 0(r11)
.text:100120E8                                addi                               r9, r9, 1
.text:100120EC                                stw                                r9, 0(r11)
.text:100120F0                                b                                loc_10012230
```

Figure 36. Vulnerable `hm_main` Code Flow

`snparse` successfully validates the initial structure of the received SNMP packet, eventually reaching the variable bindings part, where it fills a statically allocated doubly-linked list with pointers to the bindings, performing this operation until the entire packet is parsed. It is worth mentioning that the OID entries within this linked list are not parsed at that point. The number of nodes in the linked list is fixed to 20, each of them intended to hold a variable binding entry from the SNMP packet, as it is statically initialized in the stack by the `link_bindings` function.

`Sna2b` is in charge of transforming those entries into an internal structure. This structure, which is allocated in the stack, also holds additional structures, one of which is intended to

hold the OID bytes into an array that has a fixed size of `32 * sizeof(short)` (0x40 bytes).

However, `sna2b` does not validate the length of the `ASN1_OBJID` element, which is returned by `a1readlen` (red basic block in Figure 37) before invoking `a1readoid`, thus passing this potentially malicious length as a parameter (see Figure 37).




Figure 37. Code Flow with `a1readlen`

alreadyoid then assumes it has to copy the OID bytes from the variable binding entry into the fixed OBJID array (0x40 bytes) until it reaches the potentially malicious length (yellow basic block in Figure 38). As this length is an attacker-controlled value, as alreadyoid will corrupt the stack by writing controlled values (OID bytes, see Figure 40. Wireshark Dissection of Exploit Packet) out of the bounds of the aforementioned fixed OBJID array (red basic blocks in Figure 38), which can be then leveraged to execute arbitrary code.




Figure 38. Vulnerable Code Flow

We can clearly show the underlying problem if we look at certain original parts from the ‘TCP/IP illustrated v2’ code in Figure 39. As `objidlen` is controlled, `alreadoid` will end up corrupting memory in the fixed `id` array within the `objid` structure. Although the code in the Pro Line fusion `snmpd` daemon is partially different, the original vulnerability was not spotted and survived the certification process.

```

1  #define SMAXOBJID 32 /* max # of sub object ids */
2  #define OBJSUBIDTYPE unsigned short /* type of sub object ids */
3
4  struct oid { /* object identifier */
5      OBJSUBIDTYPE id[SMAXOBJID]; /* array of sub-identifiers */
6      int len; /* length of this object id */
7  };
8
9  ...
10
11 /*
12  * Each snblist node contains an SNMP binding in one of 2 forms: ASN.1
13  * encoded form or internal form. The bindings list is doubly-linked
14  */
15 struct snbentry {
16     struct oid sb_oid; /* object id in internal form */
17     struct snval sb_val; /* value of the object */
18     u_char *sb_alstr; /* ASN.1 string containing the */
19     /* object id and its value */
20     short sb_alstrlen; /* length of the ASN.1 string */
21     Bool sb_aldynstr; /* need alstr be freed/mem()ed? */
22     struct snbentry *sb_next; /* next node in the bind list */
23     struct snbentry *sb_prev; /* previous node in the list */
24 };
25
28 int
29 alreadoid(unsigned char *pack, int objidlen, struct oid *objid)
30 {
31     int val;
32     u_char *pp;
33
34     objid->len = 0;
35     pp = pack;
36
37     /* verify the required 1.3.6.1.2.1 prefix */
38     if (memcmp(MIB_PREFIX, pp, MIB_PREF_SZ)) {
39         return SYSERR;
40     }
41     pp += MIB_PREF_SZ;
42
43     for (; pp < pack + objidlen; objid->len++) {
44         if (!(*pp & CHAR_HIBIT)) {
45             objid->id[objid->len] = *pp++;
46             continue;
47         }
48         /*
49          * using long form, where bits 6 - 0 of each
50          * octet are used; (bit 7 == 0) ==> last octet
51          */
52         val = 0;
53         do
54             val = (val << 7) | (int) (*pp & ~CHAR_HIBIT);
55         while (*pp++ & CHAR_HIBIT); /* high bit set */
56         objid->id[objid->len] = val;
57     }
58     return OK;
59 }

```

Figure 39. TCP/IP Illustrated – Original Vulnerable Code

[illegible]

()

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99




Figure 41. Exploit approach

```

0012230 38 21 18 48      addi    r1, r1, 0x1848 # 0x1848 - 0xBB8 (start of bindings entries, 0x14 entries * 0xA0 size)
0012234 80 01 00 08      lwz     r0, sender_lr(r1)
0012238 7C 08 03 A6      mtlr    r0 # LR control
001223C 83 81 FF F0      lwz     r28, var_10(r1)
0012240 83 A1 FF F4      lwz     r29, var_C(r1)
0012244 83 C1 FF F8      lwz     r30, var_8(r1)
0012248 83 E1 FF FC      lwz     r31, var_4(r1)
001224C 4E 00 00 20      blr
001224C -----
# End of function .snmp_poll_requests

```

Figure 42 Gaining code execution via LR control

Although `snmpd` has been demonstrated to be vulnerable, there is still some work to do in order to verify whether it matches our requirements for remote exploitation during all phases of the flight. The first step was to analyze the conditions under which `snmpd` is launched.

The AFDR-3700's `hm_main` contains logic to handle up to six different system modes shown in Figure 43 ('Normal', 'Dataload', 'IBIT', 'InvalidStrap', 'SwValidate', and 'InvalidConfig'). Obviously, we are interested in any code that is executed under 'Normal' (id 0x11) system mode, which is the regular operational mode for the AFD-3700 DUs.

data:20003804	20 00 38 74	off_20003804:	.long	aNormal	# DATA XREF: .data:off_2000387C␣ # "Normal"
data:20003808	00 00 00 11		.long	0x11	
data:2000380C	20 00 38 68		.long	aDataload	# "Dataload"
data:20003810	00 00 00 06		.long	6	
data:20003814	20 00 38 60		.long	aIbit	# "IBIT"
data:20003818	00 00 00 0C		.long	0xC	
data:2000381C	20 00 38 50		.long	aInvalidstrap	# "InvalidStrap"
data:20003820	00 00 00 05		.long	5	
data:20003824	20 00 38 44		.long	aSwvalidate_0	# "SwValidate"
data:20003828	00 00 00 0A		.long	0xA	
data:2000382C	20 00 38 34		.long	aInvalidconfi_0	# "InvalidConfig"
data:20003830	00 00 00 09		.long	9	

Figure 43. System modes

Each supported system mode has a table of associated threads that should be created. `init_threads_for_mode` receives the current boot mode and proceeds to launch the required threads:

text:10001174	48 00 A2 8D	bl	.hm_get_sys_mode
text:10001178	4F FF FB 82	crmmove	4*cr7+so, 4*cr7+so
text:1000117C	7C 7C 1B 78	mr	r28, r3

text:100011FC		loc_100011FC:		# CODE XREF: .main+150↑j # .main+168↑j
text:100011FC				
text:100011FC	7F 83 E3 78	mr	r3, r28	
text:10001200	7F E4 FB 78	mr	r4, r31	
text:10001204	48 00 AB 61	bl	.hm_mode_initialization	
text:10001208	4F FF FB 82	crmmove	4*cr7+so, 4*cr7+so	
text:1000120C	7F 83 E3 78	mr	r3, r28	
text:10001210	7F E4 FB 78	mr	r4, r31	
text:10001214	7F 65 DB 78	mr	r5, r27	
text:10001218	48 00 48 BD	bl	.init_threads_for_mode	

Figure 44. `init_threads_for_mode`

For the Normal system mode, we have the following threads:

text:1003BA74	00 00 00 11	.long	0x11	# Boot Mode - Normal id 0x11
text:1003BA78	00 00 00 00	.long	0	# 20hz thread
text:1003BA7C	00 00 00 01	.long	1	# 1hz thread
text:1003BA80	00 00 00 02	.long	2	# Lifecycle thread
text:1003BA84	00 00 00 03	.long	3	# RAM test thread
text:1003BA88	00 00 00 05	.long	5	# Error data thread
text:1003BA8C	00 00 00 09	.long	9	# Dataload detect thread
text:1003BA90	00 00 00 07	.long	7	# CIO thread
text:1003BA94	00 00 00 06	.long	6	*** snmpd thread ***
text:1003BA98	00 00 00 08	.long	8	# Processor Sync Thread
text:1003BA9C	00 00 00 0A	.long	0xA	# end marker

Figure 45. Normal System Mode Threads

Thread ID 6 corresponds to the `snmpd` thread:

data:20000BBC	00 00 00 96	.long	0x96	
data:20000BC0	00 00 00 06	.long	6	# thread id
data:20000BC4	00 00 00 56	.long	0x56	
data:20000BC8	00 00 00 04	.long	4	
data:20000BCC	20 00 A4 60	.long	snmpd	
data:20000BD0	20 00 0A 98	.long	_hmthreadcontrol.rw_c_0	
data:20000BD4	20 00 CC 68	.long	unk_2000CC68	
data:20000BD8	00 00 00 01	.long	1	
data:20000BDC	00 00 00 00	.long	0	
data:20000BE0	00 00 00 00	.long	0	
data:20000BE4	00 00 00 00	.long	0	
data:20000BE8	20 00 0C D8	.long	aSnmpCycleSlip	# "SNMP cycle slip"

Figure 46. Thread Structure

`init_threads_for_mode` dereferences the corresponding thread table for the current system mode, initializes the list of active threads, and creates them.

.text:10005CB4	4F FF FB 82	crmove	4*cr7+so, 4*cr7+so
.text:10005CB8	57 9C F8 7E	srwi	r28, r28, 1 # r28 = boot mode = 0x11
.text:10005CBC	2C 9C 00 08	cmpwi	cr1, r28, 8
.text:10005CC0	7C 00 00 26	mfcrr	r0
.text:10005CC4	54 00 2F FE	extrwi	r0, r0, 1,4
.text:10005CC8	7C 00 00 D0	neg	r0, r0
.text:10005CCC	7F 89 00 38	and	r9, r28, r0
.text:10005CD0	7C 00 00 F8	not	r0, r0
.text:10005CD4	54 00 07 7E	clrlwi	r0, r0, 29
.text:10005CD8	7D 3C 03 78	or	r28, r9, r0
.text:10005CDC	7F 79 DB 78	mr	r25, r27
.text:10005CE0	81 22 03 44	lwz	r9, threads_per_mode_TC # _hmthreadcontrol.rw_c
.text:10005CE4	57 80 08 3C	slwi	r0, r28, 1
.text:10005CE8	7C 00 E2 14	add	r0, r0, r28
.text:10005CEC	54 00 10 3A	slwi	r0, r0, 2
.text:10005CF0	7C 1C 00 50	subf	r0, r28, r0
.text:10005CF4	54 0A 10 3A	slwi	r10, r0, 2
.text:10005CF8	39 29 00 04	addi	r9, r9, 4
.text:10005CFC	7C 09 50 2E	lwzx	r0, r9, r10 # dereference thread table for normal boot mode

Figure 47. Dereferencing thread table




Figure 48. Creating Thread

At this point, we have just confirmed that the `hm_main` application running under regular conditions (Normal system mode) launches the vulnerable `snmpd` daemon.




Figure 49. snmpd Code

As shown in Figure 49, there is no check for either a discrete or a specific condition before reaching the starting point for our vulnerability, which is the red basic block (`snmp_poll_requests`); however, there is still a verification step we have to perform, as we do not yet know how sockets are handled in the AFD-3700.

AFD-3700 Inter-Partition Communication Mechanisms and Network Connectivity

The `snmpd` thread code described above shows a socket API logic that seems pretty similar to the one implemented in Microsoft Windows systems, even using the same function names, such as `WSAGetLastError`, or error codes.

If we pay attention to the VCT file (see Figure 50), we will also find that at line 27 the `NetworkInterface` parameter is `Winsock2.2`, which may initially be surprising.

```
27 NetworkInterface=Winsock2.2; ..... // VCT173
28 ColdStartSchedule=; // VCT174
29 ColdStartDuration=0; // VCT175
30 RunTimeSchedule=0[1] 1[3] 2[7] 3[12] 5[2] 0[2] 1[2] 2[8] 3[11] 5[2]; // VCT178
31
32 // Virtual Machine Table
33 // Virtual Machine Table
34 // Virtual Machine Table
35
36 <VM0> // VCT78
37 GroupIds=; // VCT1187
38 LogicalName=AFDR-3700; // VCT1188
39 CommandLine=/usr/bin/app_launcher; // VCT1189
40 EnvironmentVars=HealthMonitorIndex=255
41 Field_Load_Id_List = AFDR:IMAT:ICIT:RTSA:EICAS:ECDA:OMSA:ODLA:OMST:ECL-DB:OMSTAR
42 PctPathFname=/usr/etc/vm0.pct; // VCT1190
```

Figure 50. S1-SL03 VCT File

The explanation behind this move seems to be found in the paper “Commercially available, DO-178B level a certifiable, hard partitioned, posix compliant real-time operating system and TCP/UDP compliant ethernet stack software”⁴¹ published by LynxWorks and Rockwell Collins in 2003. This publication provides an interesting glimpse into the requirements of those Collins avionics products relying on LynxOS-178.

⁴¹ <https://ur.booksc.eu/book/31018525/f88b3c>

POSIX / Winsock

LynxOS-178 is a POSIX-compatible operating system based on the LynxOS RTOS. LynxOS was strategically subsetted to retain key functionality while minimizing the amount of development code that goes through the expensive process of Level A verification. In this case, strategically subsetting refers to comparing POSIX functionality with avionics requirements in order to determine what POSIX functionality is not required. With the POSIX compatibility, a development environment, subsetted in the same way, can be set up on a workstation. Because a goal of the POSIX standard is to maximize source code reuse across different platforms, applications can initially be developed and tested on a development platform prior to transitioning to a target platform. Additionally, POSIX-aware developers will be able to jump right into developing on the LynxOS-178 system with minimal additional training, reducing project startup costs.

Lynx Certifiable Stack (LCS) uses a strategically subsetted version of the WinSock2 API and an appropriate subset of TCP/UDP/IP RFCs to allow applications to communicate with other

applications over a network. In this case, strategic subsetting refers to implementing most, but not all of the functions within the WinSock2 API. Some features of the API, such as indefinite blocking, do not exist within LCS because DO-178B guidance requires the components to act in a deterministic manner. Since indefinite blocking violates this requirement, a configured blocking timeout is used in its place.

Deterministic Hard Partitioned Design

LynxOS-178

Systems in an avionics environment, must behave in a deterministic manner. This means that each component within the system must be analyzable and worst-case bounded. Many factors can affect the deterministic nature of a component. When dealing with an operating system running on an LRU, it quickly becomes evident that to maintain determinism of individual components, those components must be isolated from each other in a manner that ensures determinism. The LynxOS-178 method of achieving this is to use hard, or brick-wall partitioning as shown in Figure 2 below.

Modularity

Because of the WinSock2 interface provided by the LCS package, a standardized interface exists for component interconnectivity. New components can be added to the system based on this published, standardized interface, simplifying the process of third-party vendors developing compatible components and reducing overall system upgrade costs.

Figure 51. Extracted from LynxWorks and Rockwell Collins Avionics Paper⁴²

As it is required to assess the feasibility of the discovered vulnerabilities, the underlying stack logic has been fully reverse engineered to completely understand and characterize the configured communication flows between partitions as well as those coming from the Avionics System LAN.

We now briefly introduce the components involved, then we will fully elaborate their functionalities and interactions based on the network configuration.

⁴² <https://ur.booksc.eu/book/31018525/f88b3c>

- AFDX ASL driver (`afdx_asl_drv.obj`): Implements the vast majority of the logic behind the inter-partition communication mechanism and the AFDX network capabilities.
- PCIE driver (`pcie.dldd`): Implements the End-System part, providing the low-level layers to enable the AFD-3700 DUs to communicate with the Avionics System LAN.
- `network.cfg`: Proprietary binary file; contains the complete configuration AFD-
AFDX_asl_driver.obj and PCIE.dldd rely on to allow/deny communication flows between the different partitions and with other components in the Avionics System LAN.

Figure 52 provides a detailed overview of the architecture.




Figure 52. Network and Inter-Partition Communication Architecture

network.cfg Analysis

This file could be parsed based on the reverse engineered logic found in the AFDX and PCIE drivers. This configuration file provides the deterministic rules to be implemented in the ASL.

At boot, when the AFDX driver's `install` entry point is invoked (see Figure 53), it looks for certain information from the mapped INFO file (`/usr/etc/afdx_asl_info_0`) which, for example, includes whether it has to perform some verifications or the path to the network configuration file (`network.cfg`). It proceeds to load, parse, and generate the configuration tables that will be used at runtime.

```
text:00002F34 7C 08 02 A6 mflr r0
text:00002F38 93 81 FF F0 stw r28, var_10(r1)
text:00002F3C 93 A1 FF F4 stw r29, var_C(r1)
text:00002F40 93 C1 FF F8 stw r30, var_8(r1)
text:00002F44 93 E1 FF FC stw r31, var_4(r1)
text:00002F48 90 01 00 08 stw r0, sender_lr(r1)
text:00002F4C 94 21 FF B0 stwu r1, sender_sp(r1)
text:00002F50 7C 7C 1B 78 mr r28, r3 # mapped INFO file
text:00002F54 7C 9E 23 78 mr r30, r4
text:00002F58 81 22 01 B0 lwz r9, verification_enabled_TC # verification_enabled
text:00002F5C 88 1C 00 3F lbz r0, 0x3F(r28) # verification_enabled in INFO? (false in production)
text:00002F60 90 09 00 00 stw r0, 0(r9)
text:00002F64 80 62 01 B4 lwz r3, verify_info_TC # verify_info
text:00002F68 38 80 00 0C li r4, 0xC
text:00002F6C 48 02 40 ED bl .bzero
text:00002F70 80 41 00 14 lwz r2, 0x50+saved_toc(r1)
text:00002F74 83 E2 01 B4 lwz r31, verify_info_TC # verify_info
text:00002F78 38 00 00 00 li r0, 0
text:00002F7C 90 1F 00 04 stw r0, 4(r31)
text:00002F80 90 1F 00 08 stw r0, 8(r31)
text:00002F84 81 22 01 A8 lwz r9, curr_vm_TC # curr_vm
text:00002F88 80 62 01 B8 lwz r3, main_TC # off_27920
text:00002F8C 38 80 20 00 li r4, 0x2000
text:00002F90 80 A9 00 00 lwz r5, 0(r9)
text:00002F94 38 C0 01 F4 li r6, 0x1F4
text:00002F98 80 E2 01 BC lwz r7, LC..114_TC # aAfdxaslverific # "AfdxAslVerificationThread"
text:00002F9C 39 00 00 01 li r8, 1
text:00002FA0 39 20 00 00 li r9, 0
text:00002FA4 48 00 2E 41 bl .afdx_asl_vmos_start
text:00002FA8 4F FF FB 82 crmove 4*cr7+so, 4*cr7+so
text:00002FAC 90 7F 00 00 stw r3, 0(r31)
text:00002FB0 2C 03 FF FF cmpwi r3, -1
text:00002FB4 40 82 00 0C bne loc_2FC0
text:00002FB8 38 60 FF FF li r3, -1
text:00002FBC 48 00 01 6C b loc_3128
text:00002FC0 # -----
text:00002FC0 loc_2FC0:
text:00002FC0 38 7F 00 08 addi r3, r31, 8 # CODE XREF: .afdx_aslinstall+807j
text:00002FC4 38 80 FF FF li r4, -1
text:00002FC8 48 00 46 41 bl .afdx_asl_swait
text:00002FCC 4F FF FB 82 crmove 4*cr7+so, 4*cr7+so
text:00002FD0 81 22 01 C0 lwz r9, asl_debug_state_TC # asl_debug_state
text:00002FD4 80 1C 00 2C lwz r0, 0x2C(r28)
text:00002FD8 90 09 00 00 stw r0, 0(r9)
text:00002FDC 81 22 01 34 lwz r9, skip_tests_TC # skip_tests
text:00002FE0 80 1C 00 34 lwz r0, 0x34(r28)
text:00002FE4 90 09 00 00 stw r0, 0(r9)
text:00002FE8 38 60 00 18 li r3, 0x18
text:00002FEC 48 00 44 C1 bl .afdx_asl_sysbrk
text:00002FF0 4F FF FB 82 crmove 4*cr7+so, 4*cr7+so
text:00002FF4 7C 7F 1B 78 mr r31, r3
text:00002FF8 38 80 00 18 li r4, 0x18
text:00002FFC 48 02 40 5D bl .bzero
text:00003000 80 41 00 14 lwz r2, 0x50+saved_toc(r1)
text:00003004 88 1C 00 3B lbz r0, 0x3B(r28)
text:00003008 98 1F 00 10 stb r0, 0x10(r31)
text:0000300C 88 1C 00 3C lbz r0, 0x3C(r28)
text:00003010 98 1F 00 11 stb r0, 0x11(r31)
text:00003014 88 1C 00 3A lbz r0, 0x3A(r28)
text:00003018 98 1F 00 12 stb r0, 0x12(r31)
text:0000301C 80 1C 00 E4 lwz r0, 0xE4(r28)
text:00003020 90 1F 00 14 stw r0, 0x14(r31)
text:00003024 83 A2 01 0C lwz r29, pAfdxAslStatics_TC # pAfdxAslStatics
text:00003028 93 FD 00 00 stw r31, 0(r29)
text:0000302C 38 7C 00 40 addi r3, r28, 0x40 # path to network.cfg ('/usr/local/etc/network.cfg')
text:00003030 7F C4 F3 78 mr r4, r30
text:00003034 48 00 0A 09 bl .LoadConfigTables
```

Figure 53. AFDX ASL Driver - `install` Entry Point

The first function related to the network configuration is `LoadConfigTables` that parses a set of initial table records found in the `network.cfg` file, looking for the `normal_table` record (identified by the `0xFFFF` marker, see Figure 54).




Figure 54. Code Searching for `normal_table` Record

Once the normal table has been found, a `normal_features` configuration `SubEntry` is allocated based on the normal table's offset to the `normal_feature` entry in `network.cfg`.




Figure 55. `normal_features` `SubEntry`

The driver then tries to find the `WSA_V0` SubEntry from the previously allocated entries.

text:00003038	4F FF FB 82	crmove	4*cr7+so, 4*cr7+so
text:0000303C	2C 03 00 01	cmpwi	r3, 1
text:00003040	40 82 00 E0	bne	loc_3120
text:00003044	38 60 00 01	li	r3, 1
text:00003048	80 82 01 C4	lwz	r4, LC..121_TC # aWsa_v0 # "WSA_V0"
text:0000304C	38 A1 00 38	addi	r5, r1, 0x38
text:00003050	48 00 06 E9	bl	.GetConfigSubEntryInfo

Figure 56. Searching for `WSA_V0`

The information contained into these entries provides `LoadAslConfig` with a pointer to `CnfgTblOffsets`, which contains offsets to the different configuration tables and its number of entries, as you can in Figure 57.

01098	0006417C	000017B8	5753415F	56300000	00000000	00000000	00000000	00000000	00000000
010BC	00000000	00064154	000017B8	000000D8	00000010	00000158	00000010	000001D8	00000012
010E0	00000418	00000002	00000420	00000000	00000420	00000000	00000420	00000010	000004A0
01104	00000018	000007A0	00000000	000007A0	00000000	000007A0	00000010	000007E0	0000000F
01128	00000DF8	00000010	00000E38	00000010	000013B8	00000010	000018B8	00000000	000018B8
0114C	00000000	000018B8	00000000	000018B8	00000031	00001A40	00000003	00001A4C	00000010
01170	00001A8C	00000007	00001B88	00000002	00001BC8	00000000	00001BC8	00000000	00001BC8
01194	00000000	00001BC8	00000000	00290000	00000000	00020000	00000000	00000000	00000000
011B8	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000

Figure 57. `CnfgTblOffsets`


```

text:0000B6D4      .globl .LoadAslConfig
text:0000B6D4      .LoadAslConfig:      # CODE XREF: .afdx_aslinstall+17C↑p
text:0000B6D4      # DATA XREF: .data:ioff_284F0↓o
text:0000B6D4      .set sender_sp, -0x58
text:0000B6D4      .set var_20, -0x20
text:0000B6D4      .set var_1C, -0x1C
text:0000B6D4      .set var_18, -0x18
text:0000B6D4      .set var_14, -0x14
text:0000B6D4      .set var_10, -0x10
text:0000B6D4      .set var_C, -0xC
text:0000B6D4      .set var_8, -8
text:0000B6D4      .set var_4, -4
text:0000B6D4      .set sender_lr, 8
text:0000B6D4
text:0000B6D4      mflr      r0
text:0000B6D8      stw      r28, var_10(r1)
text:0000B6DC      stw      r29, var_C(r1)
text:0000B6E0      stw      r30, var_8(r1)
text:0000B6E4      stw      r31, var_4(r1)
text:0000B6E8      stw      r0, sender_lr(r1)
text:0000B6EC      stwu     r1, sender_sp(r1)
text:0000B6F0      li      r31, 1
text:0000B6F4      lwz      r30, CnfgTblOffsets_TC # CnfgTblOffsets
text:0000B6F8      stw      r4, 0(r30)
text:0000B6FC      lwz      r28, SckAllocCnfg_TC # SckAllocCnfg
text:0000B700      lwz      r0, 0(r4)
text:0000B704      add      r0, r4, r0
text:0000B708      stw      r0, 0(r28)
text:0000B70C      lwz      r9, RxCnfgIndexTbl_TC # RxCnfgIndexTbl
text:0000B710      lwz      r0, 8(r4)
text:0000B714      add      r0, r4, r0
text:0000B718      stw      r0, 0(r9)
text:0000B71C      lwz      r9, RxCnfgTbl_TC # RxCnfgTbl
text:0000B720      lwz      r0, 0x10(r4)
text:0000B724      add      r0, r4, r0
text:0000B728      stw      r0, 0(r9)
text:0000B72C      lwz      r9, McBufferCnfgTbl_TC # McBufferCnfgTbl
text:0000B730      lwz      r0, 0x18(r4)
text:0000B734      add      r0, r4, r0
text:0000B738      stw      r0, 0(r9)
text:0000B73C      lwz      r9, RxcRbpCnfgTbl_TC_0 # RxcRbpCnfgTbl
text:0000B740      lwz      r0, 0x20(r4)
text:0000B744      add      r0, r4, r0
text:0000B748      stw      r0, 0(r9)
text:0000B74C      lwz      r9, RxcComPortCnfgTbl_TC # RxcComPortCnfgTbl
text:0000B750      lwz      r0, 0x28(r4)
text:0000B754      add      r0, r4, r0
text:0000B758      stw      r0, 0(r9)
text:0000B75C      lwz      r9, TxCnfgIndexTbl_TC # TxCnfgIndexTbl
text:0000B760      lwz      r0, 0x30(r4)
text:0000B764      add      r0, r4, r0
text:0000B768      stw      r0, 0(r9)
text:0000B76C      lwz      r9, TxCnfgTbl_TC # TxCnfgTbl # 8
text:0000B770      lwz      r0, 0x38(r4)
text:0000B774      add      r0, r4, r0
text:0000B778      stw      r0, 0(r9)
text:0000B77C      lwz      r9, TxcRbpCnfgTbl_TC # TxcRbpCnfgTbl
text:0000B780      lwz      r0, 0x40(r4)
text:0000B784      add      r0, r4, r0
text:0000B788      stw      r0, 0(r9)
text:0000B78C      lwz      r9, TxcComPortCnfgTbl_TC # TxcComPortCnfgTbl
text:0000B790      lwz      r0, 0x48(r4)
text:0000B794      add      r0, r4, r0
text:0000B798      stw      r0, 0(r9)
text:0000B79C      lwz      r9, HostNameCnfgIndexTbl_TC # HostNameCnfgIndexTbl
text:0000B7A0      lwz      r0, 0x50(r4)

```

Figure 58. AFDX ASL Driver - LoadAslConfig Function




Figure 59. *sckAllocCnfg.bin*

Based on this information, we can see in Figure 57 that the first entry, which corresponds to the `SckAllocCnfg` table (see Figure 59), is at offset `0xD8` (starting at the `CnfgTblOffsets` offset) and it contains `0x10` entries of 8 bytes, one for each supported VM. The table itself contains the number of sockets a VM is allowed to allocate.

Following this logic, it was possible to identify the tables involved.

Table 3. *Identified tables*

Table Name	Offset	Description	Enabled
<code>SckAllocCnfg</code>	<code>0xD8</code>	Number of allowed sockets	TRUE
<code>RxCnfgIndexTbl</code>	<code>0x158</code>	A VM-based index of configured Rx entries in <code>RxCnfgTbl</code>	TRUE
<code>RxCnfgTbl</code>	<code>0x1D8</code>	Incoming Sockets allowed	TRUE
<code>McBufferCnfgTbl</code>	<code>0x418</code>	Multicast Buffer Config	TRUE
<code>RxcRbpCnfgTbl</code>	<code>0x420</code>		FALSE
<code>RxcComPortCnfgTbl</code>	<code>0x420</code>		FALSE
<code>TxCnfgIndexTbl</code>	<code>0x420</code>	A VM-based index of configured Tx entries in <code>TxCnfgTbl</code>	TRUE
<code>TxCnfgTbl</code>	<code>0x4a0</code>	Outgoing Sockets allowed	TRUE
<code>TxcRbpCnfgTbl</code>	<code>0x7A0</code>		FALSE
<code>TxcComPortCnfgTbl</code>	<code>0x7A0</code>		FALSE
<code>HostNameCnfgIndexTbl</code>	<code>0x7A0</code>	A VM-based index of configured Hostname entries in <code>HostNameCnfgTbl</code>	TRUE
<code>HostNameCnfgTbl</code>	<code>0x7E0</code>	IP And Hostname of expected hosts.	TRUE

Table Name	Offset	Description	Enabled
PortNameCnfgIndexTbl	0xDF8	A VM-based index of configured port name entries in PortNameCnfgTbl	TRUE
PortNameCnfgTbl	0xE38	Port number and Name of the configured sockets	TRUE
HostCnfgTbl	0x13b8	Default hostnames for each of the supported VM	TRUE
EdeLocalPtr	0x18B8		FALSE
EdeRemotePtr	0x18B8		FALSE
DCACnfgTbl	0x18B8		FALSE
_653PortCnfgTbl	0x18B8	List of the id for the configured ARINC653 Q/S ports	TRUE
IvmCnfgTbl	0x1A40		TRUE
_653PortNameCnfgIndexTbl	0x1A4C	A VM-based index of configured ARINC653 Q/S port name entries in 653PortNameCnfg	TRUE
_653PortNameCnfgTb	0x1a8c	Name, id and VM associated with the configured A653 Q/S ports.	TRUE
DeviceNameCnfgTbl	0x1B88	Name of the supported AFDX/PCIE pseudo-devices	TRUE
AggregatePortCnfgTbl	0x1BC8		FALSE
PogoeGeneralPtrlPtr	0x1BC8		FALSE
PogoeChannelPtr	0x1BC8		FALSE
StreamRBPCnfgTbl	0x1BC8		FALSE

HostnameCnfgTbl.bin										
0	0000FFFF	0A800300	00000000	00000000	00000000	00000000	305F332E	75736200	00000000	00000000 00000000 00000000
52	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
104	0000FFFF	0A830300	00000000	00000000	00000000	00000000	335F332E	75736200	00000000	00000000 00000000 00000000
156	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
208	0000FFFF	0A811900	00000000	00000000	00000000	00000000	64657461	696C0000	00000000	00000000 00000000 00000000
260	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
312	0000FFFF	0A811900	00000000	00000000	00000000	00000000	656E7669	726F6E60	656E7400	00000000 00000000 00000000
364	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
416	0000FFFF	0A811900	00000000	00000000	00000000	00000000	6578745F	64617461	6C6F6164	00000000 00000000 00000000
468	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
520	0000FFFF	E0E0520	00000000	00000000	00000000	00000000	66725F66	6D73315F	67756964	616E6365 5F68C000 00000000 00000000
572	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
624	0000FFFF	E0E0520	00000000	00000000	00000000	00000000	66725F66	6D73325F	67756964	616E6365 5F68C000 00000000 00000000
676	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
728	0000FFFF	0A800100	00000000	00000000	00000000	00000000	66725F68	6D5F7377	69746368	6D6F6E69 746F7200 00000000 00000000
780	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
832	0000FFFF	E0E0520	00000000	00000000	00000000	00000000	66725F69	6F635F68	6D000000	00000000 00000000 00000000
884	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
936	0000FFFF	0A800100	00000000	00000000	00000000	00000000	66E1C000	00000000	00000000	00000000 00000000 00000000
988	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
1040	0000FFFF	0A811800	00000000	00000000	00000000	00000000	696D7361	00000000	00000000	00000000 00000000 00000000
1092	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
1144	0000FFFF	0A830300	00000000	00000000	00000000	00000000	6F646C5F	64617461	6C6F6164	00000000 00000000 00000000
1196	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
1248	0000FFFF	0A811900	00000000	00000000	00000000	00000000	73756D60	61727300	00000000	00000000 00000000 00000000
1300	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
1352	0000FFFF	0A800101	00000000	00000000	00000000	00000000	746F5F73	64615F68	6C000000	00000000 00000000 00000000
1404	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
1456	0001FFFF	0A800100	00000000	00000000	00000000	00000000	70310000	00000000	00000000	00000000 00000000 00000000
1508	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000 00000000 00000000
										** Å 0_3.usb
										** É 3_3.usb
										** Å detail
										** Å environment
										** Å ext_dataload
										** Å fr_fms1_guidance_hm
										** Å fr_fms2_guidance_hm
										** Å fr_fms2_guidance_hm
										** Å fr_hm_switchmonitor
										** Å fr_ioc_hm
										** Å hm
										** Å imsa
										** É odl_dataload
										** Å summary
										** Å to_sda_hm
										** Å p1

Figure 60. Hostname Table

For the `PCIE.dlidd` driver, the approach was much the same.

```
.text:00002FE8      .globl .load_config
.text:00002FE8      .load_config:                                # CODE XREF: .pcie_driver_install+80↓p
.text:00002FE8                                             # DATA XREF: .data:load_config↓o
.text:00002FE8      .set sender_sp, -0x48
.text:00002FE8      .set var_10, -0x10
.text:00002FE8      .set var_C, -0xC
.text:00002FE8      .set var_8, -8
.text:00002FE8      .set sender_lr, 8
.text:00002FE8
.text:00002FE8      mflr      r0
.text:00002FEC      stw      r0, sender_lr(r1)
.text:00002FF0      stwu     r1, sender_sp(r1)
.text:00002FF4      lwz      r0, in_ephemeral_tbl_count_TC # 0xD8A0
.text:00002FF8      stw      r0, 0x38(r1)
.text:00002FFC      lwz      r0, in_emac_table_TC # off_BE00
.text:00003000      stw      r0, 0x3C(r1)
.text:00003004      lwz      r0, in_emac_tbl_count_TC # 0xD8A4
.text:00003008      stw      r0, 0x40(r1)
.text:0000300C      lwz      r4, in_tx_table_TC # _config.rw_c
.text:00003010      lwz      r5, in_tx_tbl_count_TC # _config.bss_c
.text:00003014      lwz      r6, in_eth_table_TC # off_BE08
.text:00003018      lwz      r7, in_eth_tbl_count_TC # 0xD89C
.text:0000301C      lwz      r8, in_rx_table_TC # dword BEA4
.text:00003020      lwz      r9, in_rx_tbl_count_TC # 0xD894
.text:00003024      lwz      r10, in_ephemeral_table_TC # off_BEAC
.text:00003028      bl       .extract_config_data
.text:0000302C
```

Figure 61. PCIE Driver - `load_config` Function

The configured tables for the PCIE driver are the following:

- `in_tx_table`
- `in_tx_tbl_count`
- `in_eth_table`
- `in_eth_table_count`
- `in_rx_table`
- `in_rx_tbl_count`
- `in_ephemeral_table`

These tables contain expected tuples of IPs and ports involved in the ASL communications the End-System expects to see.

Having this information, we now proceed to trace a socket communication to figure out whether we can claim remote/inter-partition attacks against the `snmpd` are possible.

Following the Packets

As the previous architecture diagram showed, the entire Socket Abstraction Layer is implemented over the AFDX's IOCTL interface. In this way, user-mode applications can directly talk to the AFDX driver to request operations and receive data.

The entire communication process is transparent for user-mode applications, no matter whether they are looking to communicate with another VM or a remote device through the ASL.

Through the use of ‘AFDX logical devices,’ the AFDX and PCIE drivers implement the logic that handles the socket requests depending on the source and destination of the participants.

```

text:000030B0 48 00 86 25      bl      .LoadAslConfig
text:000030B4 4F FF FB 82      crmove  4*cr7+so, 4*cr7+so
text:000030B8 7C 7E 1B 78      mr      r30, r3
text:000030BC 2C 1E 00 01      cmpwi  r30, 1
text:000030C0 40 82 00 4C      bne     loc_310C
text:000030C4 80 02 01 CC      lwz     r0, afdx_device_reg_fntab_TC # afdx_device_reg_fntab
text:000030C8 90 01 00 3C      stw     r0, 0x50+var_14(r1)
text:000030CC 80 62 01 D0      lwz     r3, LC..126_TC # aAfdx_device_re # "AFDX_DEVICE_REG_FNTAB"
text:000030D0 38 80 00 01      li      r4, 1
text:000030D4 38 A1 00 3C      addi    r5, r1, 0x50+var_14
text:000030D8 48 00 3A 6D      bl      .afdx_asl_ksetenv
text:000030DC 4F FF FB 82      crmove  4*cr7+so, 4*cr7+so
text:000030E0 2C 03 00 00      cmpwi  r3, 0
text:000030E4 40 82 00 3C      bne     loc_3120
text:000030E8 4B FF DF 1D      bl      .register_IVM # Register IVM Pseudo-Device to handle Inter-VM communications
text:000030EC 7F 83 E3 78      mr      r3, r28
text:000030F0 7F E4 FB 78      mr      r4, r31
text:000030F4 4B FF D0 4D      bl      .register_ES # not supported in King-Air configuration
text:000030F8 4B FF DE 55      bl      .register_Aggregate # not supported in King-Air configuration
text:000030FC 81 22 01 D4      lwz     r9, driver_installed_TC # driver_installed
text:00003100 93 C9 00 00      stw     r30, 0(r9)

```

Figure 62. AFDX Driver Code

As seen in Figure 62, it first registers a kernel ‘environment variable’ that contains the required function pointers to register an AFDX logical device.

These function pointers are the following:

Table 4. AFDX_DEVICE_REG_FNTAB

Offset	Value
0	NULL
4	afdx_device_register
8	unregister_device
0xC	enable_device
0x10	disable_device
0x14	get_device_config
0x18	get_device_test_config

It proceeds to call `register_IVM`, `register_ES` (see Figure 66), and `register_Aggregate`; however, a logical device will only be successfully registered and enabled when it is present in the `DeviceNameCnfgTbl`.

```

ext:00004950                                .globl .register_device
ext:00004950                                .register_device:                # CODE XREF: .register_ES+188↑p
ext:00004950                                # .register_ES+1A4↑p ...
ext:00004950                                .set sender_sp, -0x58
ext:00004950                                .set var_1C, -0x1C
ext:00004950                                .set var_18, -0x18
ext:00004950                                .set var_14, -0x14
ext:00004950                                .set var_10, -0x10
ext:00004950                                .set var_C, -0xC
ext:00004950                                .set var_8, -8
ext:00004950                                .set var_4, -4
ext:00004950                                .set sender_lr, 8
ext:00004950
ext:00004950 7C 08 02 A6                                mflr        r0
ext:00004954 93 21 FF E4                                stw         r25, var_1C(r1)
ext:00004958 93 41 FF E8                                stw         r26, var_18(r1)
ext:0000495C 93 61 FF EC                                stw         r27, var_14(r1)
ext:00004960 93 81 FF F0                                stw         r28, var_10(r1)
ext:00004964 93 A1 FF F4                                stw         r29, var_C(r1)
ext:00004968 93 C1 FF F8                                stw         r30, var_8(r1)
ext:0000496C 93 E1 FF FC                                stw         r31, var_4(r1)
ext:00004970 90 01 00 08                                stw         r0, sender_lr(r1)
ext:00004974 94 21 FF A8                                stwu        r1, sender_sp(r1)
ext:00004978 7C 7B 1B 78                                mr          r27, r3
ext:0000497C 7C 9A 23 78                                mr          r26, r4
ext:00004980 7C BD 2B 78                                mr          r29, r5
ext:00004984 7C D9 33 78                                mr          r25, r6
ext:00004988 4B FF FE C9                                bl          .getDeviceIndex

```

Figure 63. PCIE Driver - register_device Function


```

text:00004850                                .globl .getDeviceIndex
text:00004850                                .getDeviceIndex:                # CODE XREF: .register_device+38↓p
text:00004850                                # DATA XREF: .data+off_27F70↓o
text:00004850                                .set sender_sp, -0x50
text:00004850                                .set var_18, -0x18
text:00004850                                .set var_14, -0x14
text:00004850                                .set var_10, -0x10
text:00004850                                .set var_C, -0xC
text:00004850                                .set var_8, -8
text:00004850                                .set var_4, -4
text:00004850                                .set sender_lr, 8
text:00004850
text:00004850 7C 08 02 A6                                mflr        r0
text:00004854 93 41 FF E8                                stw         r26, var_18(r1)
text:00004858 93 61 FF EC                                stw         r27, var_14(r1)
text:0000485C 93 81 FF F0                                stw         r28, var_10(r1)
text:00004860 93 A1 FF F4                                stw         r29, var_C(r1)
text:00004864 93 C1 FF F8                                stw         r30, var_8(r1)
text:00004868 93 E1 FF FC                                stw         r31, var_4(r1)
text:0000486C 90 01 00 08                                stw         r0, sender_lr(r1)
text:00004870 94 21 FF B0                                stwu        r1, sender_sp(r1)
text:00004874 7C 7A 1B 78                                mr          r26, r3
text:00004878 3B 80 00 00                                li          r28, 0
text:0000487C 63 9C FF FF                                ori         r28, r28, 0xFFFF
text:00004880 3B A0 00 00                                li          r29, 0
text:00004884 81 22 01 54                                lwz         r9, CnfgTblOffsets_TC # CnfgTblOffsets
text:00004888 81 29 00 00                                lwz         r9, 0(r9)
text:0000488C A3 C9 00 B6                                lhz         r30, 0xB6(r9) # Number of entries in the DeviceNameCnfgTbl
text:00004890 2C 1E 00 00                                cmpwi       r30, 0
text:00004894 41 82 00 90                                beq         loc_4924
text:00004898 7C 1D F0 10                                subfc       r0, r29, r30
text:0000489C 38 00 00 00                                li          r0, 0
text:000048A0 7C 00 01 14                                adde        r0, r0, r0
text:000048A4 6B C9 FF FF                                xori       r9, r30, 0xFFFF
text:000048A8 7D 29 00 D0                                neg         r9, r9
text:000048AC 55 29 0F FE                                srwi       r9, r9, 31
text:000048B0 7C 0B 48 39                                and.        r11, r0, r9
text:000048B4 41 82 00 70                                beq         loc_4924
text:000048B8 83 62 02 60                                lwz         r27, DeviceNameCnfgTbl_TC # DeviceNameCnfgTbl
text:000048BC
text:000048BC loc_48BC:                                # CODE XREF: .getDeviceIndex+D0↓j
text:000048BC 7C 1D F2 14                                add         r0, r29, r30 # iterates the DeviceNameConfigTbl
text:000048C0 54 1F F8 7E                                srwi       r31, r0, 1
text:000048C4 57 E0 28 34                                slwi       r0, r31, 5
text:000048C8 80 9B 00 00                                lwz         r4, 0(r27)
text:000048CC 7F 43 D3 78                                mr          r3, r26
text:000048D0 7C 84 02 14                                add         r4, r4, r0
text:000048D4 48 01 0D 9D                                bl         .internal_strcmp # Check Device Name
text:000048D8 4F FF FB 87                                cmovne     r4, r4, r0

```

Figure 64. PCIE Driver - getDeviceIndex Function

In our current configuration there are only two entries (logical devices) in DeviceNameCnfgTbl: 'EPCI' and 'IVM' .



Offset	Value	DeviceName
0	45504349 00000000 00000000 00000000	EPCI
49564D00	00000000 00000000 00000000 00000000	IVM

Figure 65. DeviceNameCnfgTbl.bin

Thus, register_ES and register_Aggregate will fail as they are trying to register 'ES_0' and 'POGOE_ES_0', which are not supported in the current configuration.

```

text:000002B0 80 41 00 14      lwz     r2, 0x2F8+saved_toc(r1)
text:000002B4 3B A1 00 D8      addi    r29, r1, 0xD8
text:000002B8 80 62 00 FC      lwz     r3, es_asic_string_TC # _afdxdrv.rw_c_0 # "ES_0"
text:000002BC 38 81 01 28      addi    r4, r1, 0x128
text:000002C0 7F A5 EB 78      mr      r5, r29
text:000002C4 80 DC 00 00      lwz     r6, 0(r28)
text:000002C8 48 00 46 89      bl      .register_device
text:000002CC 4F FF FB 82      crmove  4*cr7+so, 4*cr7+so
text:000002D0 7C 7E 1B 78      mr      r30, r3
text:000002D4 80 62 01 04      lwz     r3, pogoe_string_TC # aPogoe_es_0 # "POGOE_ES_0"
text:000002D8 38 81 00 F0      addi    r4, r1, 0xF0
text:000002DC 7F A5 EB 78      mr      r5, r29
text:000002E0 80 DC 00 00      lwz     r6, 0(r28)
text:000002E4 48 00 46 6D      bl      .register_device

```

Figure 66. register_ES

```

ext:00000FAC 83 E2 01 74      lwz     r31, aggregate_device_index_TC # aggregate_device_index
ext:00000FB0 80 62 01 78      lwz     r3, aggregate_name_TC # aAggregate # "AGGREGATE"
ext:00000FB4 38 81 00 38      addi    r4, r1, 0x38
ext:00000FB8 38 A0 00 00      li      r5, 0
ext:00000FBC 38 C0 00 00      li      r6, 0
ext:00000FC0 38 E0 00 00      li      r7, 0
ext:00000FC4 48 00 3D 85      bl      .afdx_device_register

```

Figure 67. register_Aggregate

On the other hand, as 'IVM' is present in the `DeviceNameCnfgTbl` configuration, `register_IVM` (see Figure 68) will be able to register its logical device, which implements the ARINC653 Queuing/Sampling ports for inter-VM communication.

```

text:00001004
text:00001004      .register_IVM:                                # CODE XREF: .afdx_aslinstall+1B4jp
text:00001004                                             # DATA XREF: .data:off_279C04o
text:00001004
text:00001004      .set sender_sp, -0x78
text:00001004      .set var_40, -0x40
text:00001004      .set var_3C, -0x3C
text:00001004      .set var_38, -0x38
text:00001004      .set var_34, -0x34
text:00001004      .set var_30, -0x30
text:00001004      .set var_2C, -0x2C
text:00001004      .set var_28, -0x28
text:00001004      .set var_24, -0x24
text:00001004      .set var_20, -0x20
text:00001004      .set var_1C, -0x1C
text:00001004      .set var_18, -0x18
text:00001004      .set var_14, -0x14
text:00001004      .set var_10, -0x10
text:00001004      .set var_C, -0xC
text:00001004      .set var_4, -4
text:00001004      .set sender_lr, 8
text:00001004
text:00001004 7C 08 02 A6      mflr      r0
text:00001008 93 E1 FF FC      stw       r31, var_4(r1)
text:0000100C 90 01 00 08      stw       r0, sender_lr(r1)
text:00001010 94 21 FF 88      stwu      r1, sender_sp(r1)
text:00001014 80 02 01 7C      lwz       r0, Create_QueueingPort_Ivm_TC # off_285E0
text:00001018 90 01 00 38      stw       r0, 0x38(r1)
text:0000101C 80 02 01 80      lwz       r0, Send_Queueing_Ivm_TC # off_28600
text:00001020 90 01 00 3C      stw       r0, 0x3C(r1)
text:00001024 80 02 01 84      lwz       r0, Receive_Queueing_Ivm_TC # off_28620
text:00001028 90 01 00 40      stw       r0, 0x40(r1)
text:0000102C 80 02 01 88      lwz       r0, GetPortStatus_Queueing_Ivm_TC # off_28650
text:00001030 90 01 00 44      stw       r0, 0x44(r1)
text:00001034 80 02 01 8C      lwz       r0, Purge_QueueingPort_Ivm_TC # off_285F0
text:00001038 90 01 00 48      stw       r0, 0x48(r1)
text:0000103C 80 02 01 90      lwz       r0, Create_SamplingPort_Ivm_TC # off_285D0
text:00001040 90 01 00 4C      stw       r0, 0x4C(r1)
text:00001044 80 02 01 94      lwz       r0, Write_Sampling_Ivm_TC # off_28610
text:00001048 90 01 00 50      stw       r0, 0x50(r1)
text:0000104C 80 02 01 98      lwz       r0, Read_Sampling_Ivm_TC # off_28630
text:00001050 90 01 00 54      stw       r0, 0x54(r1)
text:00001054 80 02 01 9C      lwz       r0, GetPortStatus_Sampling_Ivm_TC # off_28640
text:00001058 90 01 00 58      stw       r0, 0x58(r1)
text:0000105C 80 02 00 C4      lwz       r0, CreateStreamingPort_RBP_TC # off_283F0
text:00001060 90 01 00 5C      stw       r0, 0x5C(r1)
text:00001064 80 02 00 C8      lwz       r0, SendStreamingData_RBP_TC # off_28410
text:00001068 90 01 00 60      stw       r0, 0x60(r1)
text:0000106C 80 02 00 CC      lwz       r0, ReceiveStreamingData_RBP_TC # off_28400
text:00001070 90 01 00 64      stw       r0, 0x64(r1)
text:00001074 80 02 00 D0      lwz       r0, GetStreamingPortStatus_RBP_TC # off_28420
text:00001078 90 01 00 68      stw       r0, 0x68(r1)
text:0000107C 80 02 00 D4      lwz       r0, ResetStreamingPort_RBP_TC # off_28430
text:00001080 90 01 00 6C      stw       r0, 0x6C(r1)
text:00001084 83 E2 01 A0      lwz       r31, ivm_device_index_TC # ivm_device_index
text:00001088 80 62 01 A4      lwz       r3, ivm_string_TC # aIvm # "IVM"
text:0000108C 38 81 00 38      addi      r4, r1, -0x38
text:00001090 38 A0 00 00      li        r5, 0
text:00001094 38 C0 00 00      li        r6, 0
text:00001098 48 00 38 B9      bl        .register_device
text:0000109C 4F FF FB 82      crmove    4*cr7+so, 4*cr7+so
text:000010A0 90 7F 00 00      stw       r3, 0(r31)
text:000010A4 38 00 00 00      li        r0, 0
text:000010A8 60 00 FF FF      ori       r0, r0, 0xFFFF
text:000010AC 7C 03 00 00      cmpw     r3, r0
text:000010B0 41 82 00 14      beq       loc_10C4
text:000010B4 A0 7F 00 02      lhz       r3, 2(r31)
text:000010B8 38 80 00 00      li        r4, 0
text:000010BC 48 00 3B 2D      bl        .enable_device

```

Figure 68. register IVM⁴³

⁴³ Reliable Burst Protocol (RBP) is a proprietary protocol developed by Rockwell Collins with similarities to TCP. There is almost no public information on RBP. The AFDR-3700 supports this protocol.
<https://ieeexplore.ieee.org/document/5655316>

The PCIE driver operates in the same way to register its 'EPCI' device. It gets the AFDX_DEVICE_REG_FNTAB pointer and proceeds to register the device with the required functions to handle those ARINC653 Queuing/Sampling ports that require communication over the AFDX network (ASL).

```

.text:0000AB5C .globl .afdx_device_install
.text:0000AB5C .afdx_device_install: # CODE XREF: .pcie_install+1D4↑p
.text:0000AB5C # DATA XREF: .data:afdx_device_install↓o
.text:0000AB5C .set sender_sp, -0x48
.text:0000AB5C .set saved_toc, -0x34
.text:0000AB5C .set var_10, -0x10
.text:0000AB5C .set var_C, -0xC
.text:0000AB5C .set var_8, -8
.text:0000AB5C .set var_4, -4
.text:0000AB5C .set sender_lr, 8
.text:0000AB5C
.text:0000AB5C mflr r0
.text:0000AB60 stw r28, var_10(r1)
.text:0000AB64 stw r29, var_C(r1)
.text:0000AB68 stw r30, var_8(r1)
.text:0000AB6C stw r31, var_4(r1)
.text:0000AB70 stw r0, sender_lr(r1)
.text:0000AB74 stwu r1, sender_sp(r1)
.text:0000AB78 mr r29, r3
.text:0000AB7C lwz r3, LC..2_TC # aAfdx_device_re # "AFDX_DEVICE_REG_FNTAB"
.text:0000AB80 lwz r4, device_reg_fntab_TC # _afdxentrypoints.rw_c
.text:0000AB84 li r5, 4
.text:0000AB88 bl .kgetenv
.text:0000AB8C lwz r2, 0x48+saved_toc(r1)
.text:0000AB90 cmpwi r3, 0
.text:0000AB94 bne loc_ACCC
.text:0000AB98 lwz r28, device_reg_fntab_TC # _afdxentrypoints.rw_c
.text:0000AB9C lwz r11, 0(r28)
.text:0000ABA0 lwz r9, 0(r11)
.text:0000ABA4 cmpwi r9, 0
.text:0000ABA8 bne loc_ACCC
.text:0000ABAC lwz r4, device_fntab_TC # _afdxentrypoints.bss_c
.text:0000ABB0 lwz r0, pcie_create_port_TC # pcie_create_port
.text:0000ABB4 stw r0, 0(r4)
.text:0000ABB8 lwz r0, pcie_send_message_TC # pcie_send_message
.text:0000ABBC stw r0, 4(r4)
.text:0000ABC0 lwz r0, pcie_rcv_message_TC # pcie_rcv_message
.text:0000ABC4 stw r0, 8(r4)
.text:0000ABC8 lwz r0, pcie_get_status_TC # pcie_get_status
.text:0000ABCC stw r0, 0xC(r4)
.text:0000ABD0 stw r9, 0x10(r4)
.text:0000ABD4 stw r9, 0x14(r4)
.text:0000ABD8 stw r9, 0x18(r4)
.text:0000ABDC stw r9, 0x1C(r4)
.text:0000ABE0 stw r9, 0x20(r4)
.text:0000ABE4 lwz r0, 4(r11)
.text:0000ABE8 lwz r3, LC..10_TC # aEpci # "EPCI"
.text:0000ABEC lwz r5, device_config_TC # 0xD910
.text:0000ABF0 li r6, 0
.text:0000ABF4 li r7, 1
.text:0000ABF8 mr r8, r0
.text:0000ABFC stw r2, 0x48+saved_toc(r1)
.text:0000AC00 lwz r10, 0(r8)
.text:0000AC04 lwz r2, 4(r8)
.text:0000AC08 mtlr r10
.text:0000AC0C lwz r11, 8(r8)
.text:0000AC10 blr

```

Figure 69. PCIE Driver

Finding the Path to snmpd

Both the AFDX and PCIE drivers have the ARINC 653 Queuing/Sampling ports logic implemented, but as seen in the diagram below, the Socket Abstraction Layer is implemented on top of this layer in the AFDX driver.

The entire sequence required to reach the `snmpd` daemon from both inter-partition and the Avionics System LAN perspective follows.

WSAStartup

As with a Windows process, when any of the AFDR-3700 applications wants to use 'Winsock API version 2.2' it has to first initialize it by calling WSAStartup.

```
text:000263C8 .csect _spistart.rw_c[RO]
text:000263C8 52 6F 63 6B+ _spistart.rw_c: .string "Rockwell-Collins CoRE - AFDX_ASL WinSock API Version 2.2\n"
text:000263C8 77 65 6C 6C+ # DATA XREF: .WSPStartup+160fo
text:000263C8 2D 43 6F 6C+ # .data:LC..5_TC_0io
text:000263C8 6C 69 6E 73+ .byte 0
text:00026402 00 00 .short 0
text:00026404 41 46 44 58+aAfdx_aslDriver: .string "AFDX_ASL Driver ID: "
text:00026404 5F 41 53 4C+ # DATA XREF: .WSPStartup+180fo
text:00026404 20 44 72 69+ # .data:LC..7_TC_0io
text:00026404 76 65 72 20+ .byte 0
text:00026419 00 00 00 .byte 0, 0, 0
text:0002641C 31 2E 36 00 a1_6: .string "1.6"
text:0002641C # DATA XREF: .WSPStartup+1A0fo
text:0002641C # .data:LC..9_TC_0io
```


Figure 70. WSAStartup

Here we find the first check, as previously mentioned, WSAStartup checks whether the VM invoking the function is allowed to even create a socket.

```
text:0000DE28
text:0000DE28 loc_DE28: # CODE XREF: .WSPStartup+5Cfj
text:0000DE28 81 22 01 A8 lwz r9, curr_vm_TC # curr_vm
text:0000DE2C 81 69 00 00 lwz r11, 0(r9)
text:0000DE30 81 22 01 AC lwz r9, SckAllocCnfg_TC # SckAllocCnfg
text:0000DE34 81 29 00 00 lwz r9, 0(r9)
text:0000DE38 55 6B 18 38 slwi r11, r11, 3
text:0000DE3C 7D 4B 4A 14 add r10, r11, r9
text:0000DE40 7C 0B 4A 2E lhzx r0, r11, r9
text:0000DE44 2C 00 00 00 cmpwi r0, 0
text:0000DE48 40 82 00 10 bne loc_DE58
text:0000DE4C A0 0A 00 02 lhz r0, 2(r10)
text:0000DE50 2C 00 00 00 cmpwi r0, 0
text:0000DE54 41 82 00 34 beq loc_DE88
text:0000DE58
```

Figure 71. SckAllocCnfg

According to sckAllocCnfg (each entry is 8 bytes) only VM0 (0x29 sockets) and VM1 (2 sockets) will be able to allocate sockets.



Address	Value
00	00290000 00000000
08	00020000 00000000
10	00000000 00000000
18	00000000 00000000
20	00000000 00000000
28	00000000 00000000
30	00000000 00000000
38	00000000 00000000
40	00000000 00000000
48	00000000 00000000
50	00000000 00000000
58	00000000 00000000
60	00000000 00000000
68	00000000 00000000
70	00000000 00000000
78	00000000 00000000

Figure 72. sckAllocCnfg.bin

The following functions comprise the AFDX_ASL Winsock2 API (see Figure 73), which are available through the AFDX's driver IOCTL entry point.



Figure 73. AFDX_ASL Winsock2 API Functions

Create Socket

After calling `WSAStartup`, `snmpd` will try to open a socket at the port 161 to attend SNMP requests. This ends up invoking `WSPSocket` (see Figure 74) which checks:

- If the Socket layer has been initialized for the VM
- The kind of socket the application is trying to create (either a UDP or RBP socket)

If everything is fine, it creates the socket, which is added to a global array of sockets.

```

ext:0000E194      loc_E194:      lwz      r30, curr_vm_TC # CODE XREF: .WSPSocket+E8↑j
ext:0000E194      83 C2 01 A8      lwz      r3, 0(r30)
ext:0000E198      80 7E 00 00      slwi     r3, r3, 4
ext:0000E19C      54 63 20 36      lwz      r29, VH_Array.P4_TC_1 # unk_33EDC
ext:0000E1A0      83 A2 04 78      add      r3, r3, r29
ext:0000E1A4      7C 63 EA 14      li       r4, -1
ext:0000E1A8      38 80 FF FF      bl       .afdx_asl_swait
ext:0000E1AC      4B FF 94 5D      crmove   4*cr7+so, 4*cr7+so
ext:0000E1B0      4F FF FB 82      mr       r3, r28
ext:0000E1B4      7F 83 E3 78      bl       .AllocateSocket
ext:0000E1B8      48 00 00 75      crmove   4*cr7+so, 4*cr7+so
ext:0000E1BC      4F FF FB 82      stw      r3, 0x50+var_18(r1)
ext:0000E1C0      90 61 00 38      lwz      r3, 0(r30)
ext:0000E1C4      80 7E 00 00      slwi     r3, r3, 4
ext:0000E1C8      54 63 20 36      add      r3, r3, r29
ext:0000E1CC      7C 63 EA 14

```

Figure 74. `WSPSocket`

Bind Socket

As expected, WSPBind needs to perform several verifications according to the network configuration tables before letting the application bind a socket.

1. GetCnfgIdx uses the VM ID (0 in this case), looks into RxCnfgIndexTbl, and checks for the allowed range of entries the VM owns in RxCnfgTbl. In this current configuration, the operation that VM0 is requesting is checked against the first 0x10 entries. For VM1, the only available entry would be the last one.

```
text:00007EBC      .globl .GetCnfgIdx
text:00007EBC      .GetCnfgIdx:
text:00007EBC                                     # CODE XREF: .WSPBind+210;p
text:00007EBC                                     # .WSPSendto+360;p ...
text:00007EBC      .set sender_sp, -0x58
text:00007EBC      .set var_20, -0x20
text:00007EBC      .set var_1C, -0x1C
text:00007EBC      .set var_18, -0x18
text:00007EBC      .set var_14, -0x14
text:00007EBC      .set var_10, -0x10
text:00007EBC      .set var_C, -0xC
text:00007EBC      .set var_8, -8
text:00007EBC      .set var_4, -4
text:00007EBC      .set sender_lr, 8
text:00007EBC      .set saved_F3, 0x18
text:00007EBC      .set saved_r4, 0x1C
text:00007EBC      .set saved_r5, 0x20
text:00007EBC      7C 08 02 A6      mflr      r0
text:00007EBC      93 01 FF E0      stw       r24, var_20(r1)
text:00007EBC      93 21 FF E4      stw       r25, var_1C(r1)
text:00007EBC      93 41 FF E8      stw       r26, var_18(r1)
text:00007EBC      93 61 FF EC      stw       r27, var_14(r1)
text:00007EBC      93 81 FF F0      stw       r28, var_10(r1)
text:00007EBC      93 A1 FF F4      stw       r29, var_C(r1)
text:00007EBC      93 C1 FF F8      stw       r30, var_8(r1)
text:00007EBC      93 E1 FF FC      stw       r31, var_4(r1)
text:00007EBC      90 01 00 08      stw       r0, sender_lr(r1)
text:00007EBC      94 21 FF A8      stwu      r1, sender_sp(r1)
text:00007EBC      90 61 00 70      stw       r3, 0x58+saved_r3(r1)
text:00007EBC      90 81 00 74      stw       r4, 0x58+saved_r4(r1)
text:00007EBC      90 A1 00 78      stw       r5, 0x58+saved_r5(r1)
text:00007EBC      7C D8 33 78      mr        r24, r6
text:00007EBC      3B 40 00 00      li        r26, 0
text:00007EBC      63 5A FF FF      ori       r26, r26, 0xFFFF
text:00007EBC      38 00 27 41      li        r0, 0x2741
text:00007EBC      90 18 00 00      stw       r0, 0(r24)
text:00007EBC      A3 81 00 70      lhz       r28, 0x58+saved_r3(r1)
text:00007EBC      7C 9D 23 78      mr        r29, r4
text:00007EBC      88 01 00 73      lbz       r0, 0x58+saved_r3+3(r1)
text:00007EBC      2C 00 00 00      cmpwi     r0, 0
text:00007EBC      40 82 00 14      bne       loc_7F2C
text:00007EBC      81 22 03 6C      lwz       r9, RxCnfgIndexTbl_TC # RxCnfgIndexTbl
text:00007EBC      81 69 00 00      lwz       r11, 0(r9)
text:00007EBC      81 22 03 54      lwz       r9, RxCnfgTbl_TC # RxCnfgTbl
text:00007EBC      48 00 00 10      b         loc_7F38
text:00007EBC      # -----
text:00007EBC      loc_7F2C:
text:00007EBC                                     # CODE XREF: .GetCnfgIdx+5C7;j
text:00007EBC      81 22 03 70      lwz       r9, TxCnfgIndexTbl_TC # TxCnfgIndexTbl
text:00007EBC      81 69 00 00      lwz       r11, 0(r9)
text:00007EBC      81 22 03 64      lwz       r9, TxCnfgTbl_TC # TxCnfgTbl
text:00007EBC      loc_7F38:
text:00007EBC                                     # CODE XREF: .GetCnfgIdx+6C7;j
text:00007EBC      83 C9 00 00      lwz       r30, 0(r9)
text:00007EBC      88 01 00 72      lbz       r0, 0x58+saved_r3+2(r1)
text:00007EBC      2C 00 00 02      cmpwi     r0, 2
text:00007EBC      40 82 00 28      bne       loc_7F6C
text:00007EBC      81 22 01 A8      lwz       r9, curr_vm_TC # curr_vm
text:00007EBC      80 09 00 00      lwz       r0, 0(r9)
text:00007EBC      54 00 18 38      slwi      r0, r0, 3
text:00007EBC      7D 20 5A 14      add       r9, r0, r11
text:00007EBC      7F 2B 02 2E      lhzx      r25, r11, r0
text:00007EBC      A3 69 00 02      lhz       r27, 2(r9)
text:00007EBC      48 00 00 24      b         loc_7F84
```

Figure 75. Get Configuration Index

2. TestAndClaimConfigIndex will check the requested parameters (IPs, ports) to verify that specific socket operation matches the entries in corresponding configuration table (either RxCnfgTable or TxCnfgTable).
3. If all the checks passed, the request will be pushed down to the ARINC653 layer described previously.

```

text:0000E648      # -----
text:0000E648
text:0000E648      loc_E648:      # CODE XREF: .WSPBind+23C†j
text:0000E648      7F A3 EB 78      mr      r3, r29
text:0000E64C      38 80 00 02      li      r4, 2
text:0000E650      4B FF AE A5      bl      .createRxPorts
text:0000E654      4F FF FB 82      crmove  4*cr7+so, 4*cr7+so
text:0000E658      2C 03 00 00      cmpwi   r3, 0
text:0000E65C      41 82 FF 54      beq     loc_E5B0
text:0000E660      7F 83 E3 78      mr      r3, r28
text:0000E664      7F A4 EB 78      mr      r4, r29
text:0000E668      4B FF 9F 1D      bl      .NameSocket
text:0000E66C      4F FF FB 82      crmove  4*cr7+so, 4*cr7+so
text:0000E670      81 3B 00 00      lwz     r9, 0(r27)
text:0000E674      7D 3F 4A 14      add     r9, r31, r9
text:0000E678      A3 49 00 16      lhz     r26, 0x16(r9)
text:0000E67C      7C 1A F0 00      cmpw    r26, r30
text:0000E680      41 82 00 50      beq     loc_E6D0
text:0000E684      81 22 04 80      lwz     r9, TxCfgTbl_TC_0 # TxCfgTbl
text:0000E688      80 09 00 00      lwz     r0, 0(r9)
text:0000E68C      57 49 28 34      slwi    r9, r26, 5
text:0000E690      7D 29 02 14      add     r9, r9, r0
text:0000E694      80 69 00 08      lwz     r3, 8(r9)
text:0000E698      A0 89 00 1E      lhz     r4, 0x1E(r9)
text:0000E69C      38 A0 00 00      li      r5, 0
text:0000E6A0      38 C1 00 4C      addi    r6, r1, 0x78+var_2C
text:0000E6A4      48 00 61 A9      bl      .CreateQueueingPort_WinSock
text:0000E6A8      4F FF FB 82      crmove  4*cr7+so, 4*cr7+so
text:0000E6AC      80 61 00 4C      lwz     r3, 0x78+var_2C(r1)
text:0000E6B0      4B FF AF 59      bl      .portCreatedSuccessfully
text:0000E6B4      4F FF FB 82      crmove  4*cr7+so, 4*cr7+so
text:0000E6B8      2C 03 00 00      cmpwi   r3, 0
text:0000E6BC      41 82 FE F4      beq     loc_E5B0
text:0000E6C0      7F 83 E3 78      mr      r3, r28
text:0000E6C4      7F 44 D3 78      mr      r4, r26
text:0000E6C8      4B FF 9F 2D      bl      .AssocSocket
text:0000E6CC      4F FF FB 82      crmove  4*cr7+so, 4*cr7+so

```

Figure 76. AFDX ASL Driver - WSPBind Function

Recvfrom

snmpd is now ready to receive data from the authorized clients. When `recvfrom` is invoked, `WSPReceiveCommon` will eventually invoke `ReadQueueingMessage_WinSock`, which will receive the data from the required logical device as previously mentioned, based on the `653PortCnfgTbl` configuration (see Figure 77).

```

text:0000FBE0      loc_FBE0:      # CODE XREF: .WSPReceiveCommon+22C†j
text:0000FBE0      7F 83 E3 78      mr      r3, r28
text:0000FBE4      4B FF 9A 3D      bl      .selectNextRxIndex
text:0000FBE8      4F FF FB 82      crmove  4*cr7+so, 4*cr7+so
text:0000FBEC      7C 7D 1B 78      mr      r29, r3
text:0000FBF0      7C 1D F8 00      cmpw    r29, r31
text:0000FBF4      41 82 01 A8      beq     loc_FD9C
text:0000FBF8      A0 1C 00 9A      lhz     r0, 0x9A(r28)
text:0000FBFC      7C 00 F8 00      cmpw    r0, r31
text:0000FC00      40 82 01 38      bne     loc_FD38
text:0000FC04      93 41 00 64      stw     r26, 0x98+var_34(r1)
text:0000FC08      7C 1D EA 14      add     r0, r29, r29
text:0000FC0C      39 3C 00 50      addi    r9, r28, 0x50
text:0000FC10      7C 69 02 2E      lhzz    r3, r9, r0
text:0000FC14      38 81 00 38      addi    r4, r1, 0x98+var_60
text:0000FC18      38 A1 00 60      addi    r5, r1, 0x98+var_38
text:0000FC1C      38 C1 00 64      addi    r6, r1, 0x98+var_34
text:0000FC20      38 E0 00 01      li      r7, 1
text:0000FC24      39 01 00 68      addi    r8, r1, 0x98+var_30
text:0000FC28      48 00 4D 89      bl      .ReadQueueingMessage_WinSock

```

Figure 77. WSPReceiveCommon

Taking into account the previous information, we are now in a position to analyze `RxCnfgTbl` in order to discover from where `snmpd` is reachable.

RxCnfgIndexTbl		RxCnfgTbl							
		VM ID	Local Port	Local IP	Rule ID		Remote Port	Remote IP	MTU
00	00000010	0000003B	0A800100	0000001B	FFFF0000	00010001	4F0AFFFF	0A830300	FFFF05C0
08	00110011	0000003B	0A800100	0000001A	FFFF0000	00000001	4F0CFFFF	0A811900	FFFFFE00
10	FFFFFFFF	000000A1	0A800100	0000001C	FFFF0000	00030000	4F0F000F	0A800101	FFFF05C0
18	FFFFFFFF	000000A1	0A800100	0000001D	FFFF0000	00020000	4F09000B	0A811900	FFFF05C0
20	FFFFFFFF	00000204	0A800100	0000001E	FFFF0000	FFFFFFFF	4E3BFFFF	0A800500	FFFF0010
28	FFFFFFFF	000003E9	0A800100	0000001F	FFFF0000	FFFFFFFF	4F0E000E	0A811900	FFFF05C0
30	FFFFFFFF	0000232B	E0E0E520	00000020	FFFF0000	FFFFFFFF	4F0GFFFF	0A801900	000005B3
38	FFFFFFFF	00002465	E0E0E520	00000021	FFFF0000	FFFFFFFF	4F0HFFFF	0A801900	00010034
40	FFFFFFFF	00004F0B	0A800100	00000022	FFFF0000	FFFFFFFF	4F0A000C	0A830300	FFFF05C0
48	FFFFFFFF	00004F0D	0A800100	00000023	FFFF0000	FFFFFFFF	4F0C000D	0A811900	FFFFFE00
50	FFFFFFFF	00004F1C	0A800100	00000024	FFFF0000	FFFFFFFF	4F1D0010	0A800300	FFFFFE00
58	FFFFFFFF	00004F92	0A800100	00000025	FFFF0000	FFFFFFFF	4F930011	0A830300	FFFFFE00
60	FFFFFFFF	00004F94	0A800100	00000026	FFFF0000	FFFFFFFF	4F950012	0A830300	FFFF05C0
68	FFFFFFFF	000050B2	0A800100	00000027	FFFF0000	FFFFFFFF	50B30013	0A811800	FFFFFE00
70	FFFFFFFF	00005104	0A800100	00000028	FFFF0000	FFFFFFFF	51050014	0A811900	FFFFFE00
78	FFFFFFFF	00005106	0A800100	00000029	FFFF0000	FFFFFFFF	51070015	0A811900	FFFFFE00
		00005108	0A800100	0000002A	FFFF0000	FFFFFFFF	51090016	0A811900	FFFFFE00
		01004F0F	0A800101	00000030	FFFF0000	FFFFFFFF	00A10017	0A800100	FFFF05B3

VM0 – Entries from 0 to 0x10
VM1 – Entries from 0x11 to 0x11

Figure 78. Rx Configuration Index Table and Rx Configuration Table

According to the Rx configuration tables shown in Figure 78, the vulnerable `snmpd` can be reached both from the VM1 and from a remote node through the Avionics System LAN.

1. Inter-Partition

Rule ID: 0x1C
 Local IP: 10.128.1.0 (0xA800100)
 Local Port: 161/UDP (0xA1)
 Local Host: VM0
 Remote IP: 10.128.1.1 (0xA800101)
 Remote Port: 0x4F0F
 Remote Host: VM1

The blue arrow in Figure 78 points to Rule ID 0x30, which is the VM1 rule for the SNMP inter-partition communication between VM0 and VM1.

This entry basically contains the same parameters seen in VM0's Rule 0x1C, but in the opposite direction, as from the VM1 perspective, it is now receiving the response from the `snmpd` server in VM0.

2. Remote Node (Avionics System LAN)

Rule ID: 0x1D
 Local IP: 10.128.1.0 (0xA800100)
 Local Port: 0xA1 (161/UDP) SNMP
 Local Host: VM0
 Remote IP: 10.129.25.0 (0xA811900)
 Remote Port: 20233/UDP

Following the verification process, we find that, as expected, TxCfgTbl contains the complementary rules perfectly matching the ones described above.

		Remote		TxCfgTbl		Local			
VM ID	Port	Remote IP	Rule ID			Port	Local IP	MTU	
000	0000003B	0A811900	00000001	FFFF0000	00000016	51080010	0A800100	000005C0	
020	0000003B	0A811900	00000000	FFFF0000	00000015	5106000F	0A800100	000005C0	
040	0000003B	0A830300	00000002	FFFF0000	00000012	4F94000C	0A800100	000005C0	
060	00000045	0A800300	00000003	FFFF0000	00000010	4F1C000A	0A800100	000005C0	
080	00000045	0A811800	00000004	FFFF0000	00000013	50B2000D	0A800100	000005C0	
0A0	00000045	0A811900	00000005	FFFF0000	00000014	5104000E	0A800100	00008000	
0C0	00000045	0A830300	00000006	FFFF0000	00000011	4F92000B	0A800100	000005C0	
0E0	0000233C	0A811900	00000008	FFFF0000	0000FFFF	4E21FFFF	0A800100	000005B3	
100	0000233D	0A811900	00000009	FFFF0000	0000FFFF	4E24FFFF	0A800100	000005B3	
120	000023F2	0A811900	0000000A	FFFF0000	0000FFFF	4E22FFFF	0A800100	00000100	
140	00002580	0A800101	0000000B	FFFF0000	0000FFFF	4E25FFFF	0A800100	000005B3	
160	00004F09	0A811900	0000000C	FFFF0000	0000000F	00A10003	0A800100	000005B3	
180	00004F0A	0A830300	0000000D	FFFF0000	0000FFFF	4F0B0008	0A800100	00001CB3	
1A0	00004F0C	0A811900	0000000E	FFFF0000	0000FFFF	4F0D0009	0A800100	00001CB3	
1C0	00004F0E	0A811900	0000000F	FFFF0000	0000FFFF	03E90005	0A800100	00000200	
1E0	00004F0F	0A800101	00000010	FFFF0000	0000000B	00A10002	0A800100	000005B3	
200	00004F1D	0A800300	00000011	FFFF0000	00000003	4F1C000A	0A800100	000005C0	
220	00004F93	0A830300	00000012	FFFF0000	00000006	4F92000B	0A800100	000005C0	
240	00004F95	0A830300	00000013	FFFF0000	00000002	4F94000C	0A800100	000005C0	
260	000050B3	0A811800	00000014	FFFF0000	00000004	50B2000D	0A800100	000005C0	
280	00005105	0A811900	00000015	FFFF0000	00000005	5104000E	0A800100	00008000	
2A0	00005107	0A811900	00000016	FFFF0000	00000001	5106000F	0A800100	000005C0	
2C0	00005109	0A811900	00000017	FFFF0000	00000000	51080010	0A800100	000005C0	
2E0	010000A1	0A800100	00000018	FFFF0000	0000FFFF	4F0F0011	0A800101	000005C0	

Figure 79. Tx Configuration Table

The last verification step corresponds to PCIE's `in_rx_table`, which is checked by the EPCI logical device before routing the received message from the ASL.

```

text:000096F0      .globl .read_message
text:000096F0      .read_message:                                # CODE XREF: .pcie_rcv_message+70↓p
text:000096F0                                             # DATA XREF: .data:read_message↓o
text:000096F0      .set sender_sp, -0xA8
text:000096F0      .set var_70, -0x70
text:000096F0      .set var_6C, -0x6C
text:000096F0      .set var_68, -0x68
text:000096F0      .set var_64, -0x64
text:000096F0      .set var_60, -0x60
text:000096F0      .set var_5C, -0x5C
text:000096F0      .set var_50, -0x50
text:000096F0      .set var_4C, -0x4C
text:000096F0      .set var_48, -0x48
text:000096F0      .set var_47, -0x47
text:000096F0      .set var_46, -0x46
text:000096F0      .set var_40, -0x40
text:000096F0      .set var_3C, -0x3C
text:000096F0      .set var_34, -0x34
text:000096F0      .set var_30, -0x30
text:000096F0      .set var_2C, -0x2C
text:000096F0      .set var_28, -0x28
text:000096F0      .set var_24, -0x24
text:000096F0      .set var_20, -0x20
text:000096F0      .set var_1C, -0x1C
text:000096F0      .set var_18, -0x18
text:000096F0      .set var_14, -0x14
text:000096F0      .set var_10, -0x10
text:000096F0      .set var_C, -0xC
text:000096F0      .set var_8, -8
text:000096F0      .set var_4, -4
text:000096F0      .set sender_lr, 8
text:000096F0
text:000096F0      mflr      r0
text:000096F8      stw       r19, var_34(r1)
text:000096F8      stw       r20, var_30(r1)
text:000096FC      stw       r21, var_2C(r1)
text:00009700      stw       r22, var_28(r1)
text:00009704      stw       r23, var_24(r1)
text:00009708      stw       r24, var_20(r1)
text:0000970C      stw       r25, var_1C(r1)
text:00009710      stw       r26, var_18(r1)
text:00009714      stw       r27, var_14(r1)
text:00009718      stw       r28, var_10(r1)
text:0000971C      stw       r29, var_C(r1)
text:00009720      stw       r30, var_8(r1)
text:00009724      stw       r31, var_4(r1)
text:00009728      stw       r0, sender_lr(r1)
text:0000972C      stwu      r1, sender_sp(r1)
text:00009730      mr        r19, r4
text:00009734      mr        r20, r5
text:00009738      mr        r30, r6
text:0000973C      mr        r24, r7
text:00009740      li        r26, 0
text:00009744      li        r29, 0
text:00009748      li        r23, 0
text:0000974C      li        r25, 0
text:00009750      li        r22, 0
text:00009754      li        r31, 0
text:00009758      stw       r22, 0xA8+var_40(r1)
text:0000975C      stw       r22, 0xA8+var_3C(r1)
text:00009760      bl        .get_rx_table_entry

```

Figure 80. PCIE Driver - read_message Function

Within in_rx_table is the highlighted entry that matches the incoming snmpd rule we analyzed in the AFDX configuration tables.

```

00000001 00000000 0A802100 0A811900 003B4F0C 005A05C8
00010001 00000000 0A802100 0A836300 003B4F0A 000205C0
00020001 00000000 0A802100 0A811900 00A14F09 000205C0

```

Figure 81. PCIE.dlidd in_rx_table

Another important fact the analysis of in_rx_table and in_tx_table revealed is that there are similar entries for multiple ASL IPs, which denotes snmpd rules are also implemented for other systems different than the AFD, thus opening the door to explore additional attack vectors. It is assumed the same vulnerable 'snmpd' is used in those additional LynxOS-178-based systems (See Figure 8).

Attack Vectors for snmpd

We have two attack vectors that can be used to trigger the vulnerability during any phase of the flight: VM1 and a remote node in the Avionics System LAN (10.129.25.0).




Figure 82. Attack Vectors

1. VM1

The reason for this configured `snmpd` communication channel between VM0 and VM1 is the Simple Display Application (SDA, see Figure 83), which runs in VM1 only when a certain system mode is activated (to perform a data load operation using a USB drive). During 'Normal' system mode, VM1 is assigned to a functional application, such as the ATF-3500 or the FDSA-6500.

This fact is interesting because it leads to a significant logic vulnerability: from a network configuration perspective the system mode is not taken into account, so actually VM1 can launch an attack against VM0 regardless of the application running in VM1. As a result, if a malicious actor compromises the VM1 through methods not covered in this paper, it would be possible to launch an attack against the VM0 by leveraging a deterministic network rule intended for a different system mode.



Figure 83. SDA

2. Avionics System LAN: 10.129.25.0 in the ASL

HostNameCfgTbl can be used to resolve the IP of the potentially offending node 10.129.25.0 (0x0A811900).

HostNameCfgTbl.bin																	
0	0000FFFF	0A800300	00000000	00000000	00000000	00000000	30F3332E	75736200	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	0_3.usb
52	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	3_3.usb
104	0000FFFF	0A803000	00000000	00000000	00000000	00000000	33F3332E	75736200	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
156	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
208	0000FFFF	0A811900	00000000	00000000	00000000	00000000	64657461	696C0000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	detail
260	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
312	0000FFFF	0A811900	00000000	00000000	00000000	00000000	656E7669	726F6E6D	656E7400	00000000	00000000	00000000	00000000	00000000	00000000	00	environment
364	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
416	0000FFFF	0A811900	00000000	00000000	00000000	00000000	6578745F	64617461	6C6F6164	00000000	00000000	00000000	00000000	00000000	00000000	00	ext_dataload
468	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
520	0000FFFF	E0E0520	00000000	00000000	00000000	00000000	66725F66	6073315F	67756964	616E6365	5F686D00	00000000	00000000	00000000	00000000	00	fr_fms1_guidance_hm
572	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
624	0000FFFF	E0E0520	00000000	00000000	00000000	00000000	66725F66	6073325F	67756964	616E6365	5F686D00	00000000	00000000	00000000	00000000	00	fr_fms2_guidance_hm
676	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
728	0000FFFF	0A800100	00000000	00000000	00000000	00000000	66725F68	605F7377	69746368	606F6E69	746F7200	00000000	00000000	00000000	00000000	00	fr_hm_switchmonitor
780	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
832	0000FFFF	E0E0520	00000000	00000000	00000000	00000000	66725F69	6F635F68	6D000000	00000000	00000000	00000000	00000000	00000000	00000000	00	fr_ioc_hm
884	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
936	0000FFFF	0A800100	00000000	00000000	00000000	00000000	686D0000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	hm
988	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
1040	0000FFFF	0A811800	00000000	00000000	00000000	00000000	696D7361	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	imsa
1092	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
1144	0000FFFF	0A803000	00000000	00000000	00000000	00000000	6F646C5F	64617461	6C6F6164	00000000	00000000	00000000	00000000	00000000	00000000	00	odl_dataload
1196	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
1248	0000FFFF	0A811900	00000000	00000000	00000000	00000000	73756D6D	61727900	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	summary
1300	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
1352	0000FFFF	0A800101	00000000	00000000	00000000	00000000	746F5F73	64615F68	6D000000	00000000	00000000	00000000	00000000	00000000	00000000	00	to_sda_hm
1404	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	
1456	0001FFFF	0A800100	00000000	00000000	00000000	00000000	70310000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00000000	00	p1

Figure 84. Hostname Configuration Table

It turns out the same IP resolves to four different hostnames:

- detail
- environment
- ext_dataload
- summary

This information is quite interesting as the hostname `ext_dataload` may give some clues.

This same device is also performing TFTP operations (see either rule 0x1A in the RxCfgTable or rule 0 in in_rx_table), so it seems reasonable to guess we are talking about an ‘External Data Loader’, or a Data Loading Avionics Gateway, such as the Collins’ Information Management System (IMS)⁴⁴.

The IMS may be controlled over a WiFi connection.




Figure 85. Data Loading over WiFi⁴⁵



Figure 86. WiFi Enabled for IMS Maintenance Operations⁴⁶

⁴⁴ <https://fccid.io/AJK8223132/User-Manual/Manual-2621284>

⁴⁵ <https://www.youtube.com/watch?v=s20Xjq4HnEQ>

⁴⁶ <https://www.youtube.com/watch?v=9vNRoFKclB0>

The complete configuration is dependent of the desired connections to ancillary equipment. Figure 2-1 shows a typical configuration:




Figure 86. IMS-6010 Installation Manual⁴⁷

The installation manual for the IMS-6010 provides a diagram for a typical configuration that also matches the network traffic flows we just analyzed (see Figure 86.)

It is important to clarify that the IMS is just one of the potential attack vectors, which initially depends on the ‘on-ground’ discrete. Unfortunately, the exposed materials that enabled this research are not enough to explore the remaining attack vectors coming from the ASL.

As a result, a generic approach to reach the ASL from either external/adjacent networks or other compromised components within the network is beyond the scope of this research. The lack of access to a live target forces us to assume that there is no generic way to accomplish this required step for the different aircraft potentially affected, so those scenarios should be addressed on a case-by-case basis.

⁴⁷ <https://fccid.io/AJK8223132/Users-Manual/Manual-2621284>

Attacking AFDR-3700 Drivers

We have been describing the functionality implemented by some of the drivers without assessing the attack vectors they may pose. As we have seen, these drivers may also expose part of their functionality to user-mode through their IOCTL interfaces.

When analyzing the VCTs, we find that some of these drivers are configured without restrictive permissions. Thus, without any additional checks in the 'open' entry point, any VM would be able to communicate with the driver.

The following two vulnerabilities are used to illustrate the fact that these drivers are also prone to the same kind of vulnerabilities usually present in drivers from regular Operating Systems.

Exploiting the following vulnerabilities may allow an unprivileged VM to execute code with kernel privileges, thus gaining the ability to compromise the entire LynxOS-178 deployment. In case of a failed exploitation attempt, the attack will leave the LynxOS-178 kernel in an unstable state.

PCIE.dldd: RESET_MIB_DATA IOCTL Double Fetch

The driver fails to declare as 'volatile' an attacker-controlled variable that is used in a switch statement. As a result, internally the compiler optimizes the code in such a way that a race condition is created between 0x21B4 and 0x21C4, that can be leveraged to bypass the 'jumptable' index check at 0x21BC (see Figure 87). If the malicious threads in the offending partition win the race, it will be possible to jump to an arbitrary memory address, thus potentially executing arbitrary code within the kernel context. It is important to note that LynxOS-178 implements a deterministic scheduler, which facilitates the exploitation of these issues.

```
.text:000021A0
.text:000021A0      loc_21A0:
.text:000021A0      # CODE XREF: .pcie_ioctl+A0↑j
.text:000021A0      # DATA XREF: .pcie_ioctl:jpt_1934↑o
.text:000021A0      # jumptable 00001934 case 146
.text:000021A4      mr      r3, r30
.text:000021A8      li      r4, 4
.text:000021AC      lwz     r5, LC..60_TC # aReset_mib_data # "RESET_MIB_DATA"
.text:000021B0      bl      .check_read
.text:000021B4      cmpwi   r3, 0
.text:000021B8      bne     loc_1C38
.text:000021BC      lwz     r0, 0(r30) # first fetch
.text:000021C0      cmplwi  r0, 6 # switch 7 cases
.text:000021C4      bgt     def_21DC # jumptable 00001934 default case
.text:000021C8      lwz     r0, 0(r30) # #second fetch
.text:000021CC      lwz     r9, L..233_TC # jpt_21DC
.text:000021D0      slwi    r0, r0, 2
.text:000021D4      lwzx    r0, r9, r0
.text:000021D8      add     r0, r0, r9
.text:000021DC      mtctr   r0
.text:000021DC      bctr    # switch jump
```

Figure 87. Race Condition

The permissions applied to the driver's device (see Figure 88) leaves the attack open for any VM.

```
129 <DDD1> // VCT499
130 Type=c; // VCT200
131 DriverId=; // VCT201
132 ObjectFname=/usr/bin/pcie.dldd; // VCT202
133 InfoFname=/usr/etc/pcieinfo_policing_on_autoneg.info; // VCT203
134 NumOfMinorDevs=0; // VCT204
135 BaseCharNodeFname=/dev/ddev/pcie; // VCT205
136 BaseBlockNodeFname=; // VCT206
137 OwnerId=0; // VCT207
138 GroupId=0; // VCT208
139 Permissions=0666; // VCT209
140 </DDD1>
```

Figure 88. Driver Permissions

MERGE.dldd: Memory Corruption Due to Integer Overflow

This driver implements two different IOCTLs (0x96 and 0x97) to perform a memory copy operation from driver's internal structure to user-mode memory and vice versa. While validating the IOCTL parameters received from user-mode, the driver fails to properly verify the length, thus leading to a memory corruption scenario that may be potentially leveraged to escalate privileges (see Figure 89).




Figure 89. Merge.dldd Vulnerabilities

Conclusions

This paper has illustrated how the AFDR-3700 software plays a key role in the proper functioning of the following critical devices:

- Primary Flight Display (PFD)
- Multi-Function Display (MFD)

It has also elaborated on the fact that the integrity of functional applications that sustain safety-critical functionality, running under a compromised AFDR-3700, cannot be guaranteed.




Figure 90. Scenario for a Compromised AFDR-3700

This essentially means that a successful attack may enable the attackers to perform the following actions.

1. Display malicious information to the pilots

This maliciously generated misleading information may include data that does not actually represent the external conditions nor the internal state under which the aircraft is operating.

Disputed statement 2

Collins Aerospace explicitly communicated to IOActive in a letter dated April 7, 2022 that the ‘defects identified by IOActive cannot be used or manipulated to cause misleading information to be displayed’, also requesting this statement to be deleted from the paper, without providing any further information or technical details.

IOActive is not removing this potential attack scenario mainly due to the following reasons:

1. Among other things, a compromised AFDR-3700 grants the attacker a direct access to low-level graphic resources and video memory in the DU.
2. To facilitate further investigations on this matter.

If any additional information is received, that clearly demonstrates this initial assessment is not aligned to a correct technical analysis, IOActive will proceed to delete this scenario and publicly rectify if required.

2. Perform a destructive attack that prevents pilots from properly using the PFD/MFD

A destructive payload may be triggered at certain times, under specific conditions.

The scenarios where destructive attacks can be performed may vary, depending on whether the target is a military or a commercial aircraft.

It is worth mentioning that even in a case where the PFD/MFD may be rendered inoperable, pilots should still be able to rely on the Standby Display, which is intended to operate independently, in addition to electromechanical instruments.




Figure 91 Standby Display

Potential safety implications

The impact of these post-exploitation scenarios will be amplified if the attacks are carried out when the weather conditions force the crew to operate the aircraft according to the instrument flight rules.

As a result, it is IOActive's considered opinion that if the vulnerabilities herein described are successfully exploited, this situation may cause certain potentially unsafe conditions for the aircraft, crew, and passengers.

Disputed statement 3

Collins Aerospace explicitly communicated to IOActive in a letter dated April 7, 2022 that “contrary to the finding in your paper, after significant analysis, testing, and review, Collins has determined that the defects described do not adversely impact operational safety. Consistent with other aerospace research IOActive has undertaken, there are mitigations installed elsewhere in the aircraft architecture that ensure the defects described cannot be activated in a way that would compromise the safety of the aircraft.”

We appreciate the efforts Collins Aerospace dedicated to properly assess these issues. However, it is worth clarifying that IOActive has not been provided with any visibility on these efforts; we know nothing about the methodology, the scope of the analysis or the implemented techniques. We do not know either, where those mitigations are implemented, nor the technical details behind them.

We also consider important to note that Collins' response is also consistent with previous responses we have received, always pointing to unspecified mitigations, which have been never fully elaborated. Those mitigations are not mapped to specific vulnerabilities or attack scenarios, but proposed as a generic, abstract, concept able to foil any attack. When our previous aerospace research has covered non-certified airborne software, the mitigations were apparently in the certified avionics. Now that we are covering certified avionics, the mitigations are elsewhere.

That said, we have no reasons to not assume that those mitigations are actually in place, and working as expected. However, any serious security research initiative requires a healthy dose of questioning vague statements and paradigms, in order to confront them with reproducible, independently verifiable and consistent technical details.

If any additional information is received, which clearly demonstrates that our initial safety assessment is not aligned to a correct technical analysis, IOActive will proceed to update the paper and publicly rectify if required.

It is not the intention of this research to speculate on complete attack scenarios that may lead to a successful exploitation nor on the composition of post-exploitation payloads. That approach would require extensive information on a variety of both airborne and ground systems as well as technical details of multiple commercial, military, and business aircraft models. As IOActive does not have access to all of the information required for such conclusions, the right thing to do would be to refrain from speculating on these potential scenarios, although we have internally assessed them.

However, it also seems reasonable to raise questions around this situation. In IOActive's experience, the responses we receive from the affected entities usually suggest that these vulnerabilities do not represent an actual risk, due to how the systems are implemented, allegedly following a multilayered protection design. Although these entities do not provide further details on those additional security controls, it is usually expected that the "multiple layers" of defense before reaching the vulnerable component may include physical access control systems within highly secured facilities such as airports⁴⁸, as well as non-certified/COTS software and network devices.

The obvious concern we see is that if it were possible to discover the kind of vulnerabilities, presented in this document, in safety-critical avionics software that has been certified according to the highest level of software safety requirements, it would be difficult to assume any greater reliability in the remaining components of these multilayered systems.

Also, these conclusions do not weigh whether real-world attacks against aviation targets are a current trend, even in the current geopolitical situation. In general terms, the threats against safety-critical assets should be evaluated from the perspective that an adversary's capabilities remain consistent, but their intentions may change overnight.

It is important to point out that the extent of this research's conclusions is dictated by its inherent limitations: despite the evidence pointing toward certain scenarios, we will not claim what we cannot publicly demonstrate. On the other hand, in response to the questions this research may generate, we will certainly hope to see technically grounded answers from those who actually have those capabilities.

Finally, the technical details presented herein should be seen as a way to move past the point where "unbreakability" is still claimed for certified avionics that sustain safety-critical operations.

⁴⁸ Some of the affected aircraft, such as King Air, can be found also in local aerodromes, which are far behind in terms of physical security compared to commercial airports.

Acknowledgements

We want to thank the following external reviewers, also those who wish to remain anonymous, for their commitment to disinterestedly review this research, as well as for their valuable remarks:

- Peter Lemme
Aviation Expert
<https://www.linkedin.com/in/satcomguru>
- Inbar Raz
Aviation security researcher, VP of Research at Hunters
<https://il.linkedin.com/in/inbarraz>
- Noam Menscher
Security Researcher, Former Head of Aviation R&D at Argus Cyber Security
<https://il.linkedin.com/in/noam-menscher-233a35134>
- Eric S. Johnson
Pilot and Adjunct Instructor Computer Science, Florida International University

About Ruben Santamarta

Ruben Santamarta is experienced in network penetration and web application testing, reverse engineering, industrial control systems, transportation, RF, embedded systems, AML, vulnerability research, exploit development, and malware analysis. As a principal consultant at IOActive, Mr. Santamarta performs penetration testing, identifies system vulnerabilities, and researches cutting-edge technologies. Mr. Santamarta has performed security services and penetration tests for numerous global organizations and a wide range of financial, technical, and educational institutions. He has presented at international conferences including Ekoparty and Black Hat USA.

About IOActive

IOActive is a comprehensive, high-end information security services firm with a long and established pedigree in delivering elite security services to its customers. Our world-renowned consulting and research teams deliver a portfolio of specialist security services ranging from penetration testing and application code assessment through to semiconductor reverse engineering. Global 500 companies across every industry continue to trust IOActive with their most critical and sensitive security issues. Founded in 1998, IOActive is headquartered in Seattle, USA, with global operations through the Americas, EMEA and Asia Pac regions. Visit <https://ioactive.com> for more information. Read the IOActive Labs Research Blog: <https://labs.ioactive.com>. Follow IOActive on Twitter: <https://twitter.com/ioactive>.